


☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220810.07

BV Job nr: KHO.INI.22.SA

PROJECT: Third Party Inspection for AIR COMPRESSOR

Ref: KHO.INI.22.SA

BV Client: SUDHIR GENSETS

Manufacturer: DOOSAN

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
Visual Inspection FOR AIR COMPRESSOR	000391BCAGJ01 SAC-185-034	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by
ORIGINAL DECLARATION OF CONFORMITY	-	-	DOOSAN

INSPECTIONS :

Inspection place & Date or Period:

SUDHIR YARD 10 AUGUST 2022

Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping :☒ NoResults of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection of 1 unit of AIR COMPRESSOR was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-32383

Next visit scheduled: 09 AUG. 2023


☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220810.07

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection of 1 unit Of Air Compressor.

2. Attendees :

Mr. Hesham Elsaqa --- BV Inspector

3. Scope of Inspection :

a. Visual & Functional Inspection of AIR COMPRESSOR



1- General Data

Equipment Type	AIR COMPRESSOR
Model	C185WKU
Engine Make	KUBOTA
YOM	2022
Volume	185 CFM

2- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Previous Report by universal inspection company)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Electrical, (conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.



☐ Interim
☒ Final

INSPECTION REPORT

NO. R105220810.07

➤ **Conclusion:**

The AIR COMPRESSOR found in good condition at the time of Inspection.

Inspected by:

HESHAM ELSAQA
 IVS-Lifting Inspection

Hesham Elsaqa

Date of issue: 14 AUGUST 2022

Inspection centre: BUREAU VERITAS ALKHOBAR



Checked by:

Team Leader

[Signature]