




مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



Certificate of Thorough Visual and Functional Examination of  
Scissor Lift (MEWP)

Certificate No: JHI-8475-26-C2

Date of Inspection: 04-06-2026

Name of the owner company:  
SUDHIR EQUIPMENT RENTAL COMPANY

Location:  
RIYADH- KSA

Equipment Details: SCISSOR LIFT

Reference Regulations:

SASO-ISO-18893, BS EN 280-1 & 2 : 2022

Maker & Date of Manufacture:

DINGLI & 2024

Traffic Plate No:

N/A

Owner No.

SD12ESL-1816

Model No.

JCPT1412AC

Chassis No. / Serial No.

JPAC024H04011

Sticker No.

017475

Max. Platform height

12.0m

Max. Horizontal Reach

7.75m

Dimension LxWxH(m)

N/A

Max. Rated Capacity: 249kg(Max2Persons + Tools)

Description of Test:

Note: Visual Test Were Satisfactory.

Date of Last Examination

N/A

Date of Next Examination

03-12-2026

RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory.

\*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: M.SHEIKALLAVUDEEN

Authorized Signature: [Signature]

Surveyor's Name: RIFAY

Surveyor's Signature: [Signature]

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or property by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may be used. This certificate shall not be regarded as a full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage, loss or injury to the equipment or material.

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh, Al Malaz Dist. Po. 12831

CR No: 1010927177, Tel: 0112334900, Email: [info@jhinspection.com](mailto:info@jhinspection.com), [www.jhinspection.com](http://www.jhinspection.com)

## Annex to Certificate of Test and Thorough Examination

Certificate No.: JHI-8475-26-C2

Date of Inspection: 04-06-2026

| No. | DESCRIPTION                      | CONDITION    |
|-----|----------------------------------|--------------|
| 1.  | Equipment documents              | Satisfactory |
| 2.  | Lift cylinder                    | Satisfactory |
| 3.  | Scissor structure                | Satisfactory |
| 4.  | Tires & wheels                   | Satisfactory |
| 5.  | Hydraulic system                 | Satisfactory |
| 6.  | Electrical systems               | Satisfactory |
| 7.  | Battery condition                | Satisfactory |
| 8.  | Brake                            | Satisfactory |
| 9.  | Emergency descent                | Satisfactory |
| 10. | Horns and safety devices         | Satisfactory |
| 11. | Operational control              | Satisfactory |
| 12. | Fire extinguisher                | Satisfactory |
| 13. | Reverse alarm                    | Satisfactory |
| 14. | Revolving beacon / warning light | Satisfactory |
| 15. | Emergency stop                   | Satisfactory |
| 16. | Over all body condition          | Satisfactory |
| 17. | Reflective tape and markings     | Satisfactory |
| 18. | Maintenance records              | Satisfactory |
| 19. | General condition                | Satisfactory |

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: RIFAY



Surveyor's Signature: 

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628

CR No: 1010927177, Tel: 0112334900, Email: [hfo@jhinspection.com](mailto:hfo@jhinspection.com), [www.jhinspection.com](http://www.jhinspection.com)