

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 11-05-2025		Date of issue : 11-05-2025		Report No. : ESICO-LFT-R25-4012	
Name & Address of employer		Location		Sticker No	Standards
SUDHIR EQUIPMENT RENTALS		Riyadh		5664	SASO GSO EN 280
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name	
SD8ESL-1521 OR JPAC024F03351	SCISSOR LIFT MODEL: JCPT0807AC Max. working height: 7.80m Max. number of occupatans: 2 Machine weight: 1415kg	RATED LOAD: 230KG	2024	DINGLI	
Is this the first examination after installaton or assembly at a new site or location? Yes ☐ - ☐ No ☒		Was the examination carried out within an interval of? - 6 Months			
If the answer to the above question is YES, has the equipment been installed correctly? Yes ☐ - ☐ No ☐		In accordance with an examination scheme? Yes ☒ No ☐			
		After the occurence of exceptional circumstances? Yes ☐ - ☐ No ☒			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory					



For confirmation scan QR code
search with report number : ESICO-LFT-R25-4012

☒ Safe to operate

Next Inspection : 10-11-2025

Inspected by : Mohamed Askar Ali



10056897



EP-Q4634



1100004098



33564



10739



001052261



05022531

