

CERTIFICATE OF INSPECTION – SCISSOR LIFT

Certificate No.	RY-26/97283	Field Inspection Report	52856
Inspection Date	January 06, 2026	Issue Date	January 06, 2026
Inspection Type	Thorough	Next Inspection Date	July 05, 2026
Equipment Owner	OCEANSHORE ARABIA, Kingdom of Saudi Arabia.		
Work Location	Haramain Makkah, Kingdom of Saudi Arabia.		
Standard Reference	SASO GSO EN 280 – ANSI A.92.6: 2019 – ISO 18893:2024		
Manufacturer Name	DINGLI	Year of Manufacture	2025
Serial No. / VIN	JPAC025D00726	Registration Plate No.	N/A
Model No.	JCPT0807AC	Company No.	SD8ESL-2402
Sticker No.	87209	Last Inspection Date	July 08, 2025
Age of Equipment from Year of Manufacture	N/A		

Description & Remarks	Rated Capacity
Working Height. 7.8 – Meters. Platform Height. 5.8 – Meters. Visual inspection and functional tests were Satisfactory and free from apparent defects. Any major repair will cause the cancelation of this certificate & equipment needs to be inspected again.	230 – Kg.

Reason For Examination

A 3-months	B 6-months	C 12-months	D Written Scheme	E Exceptional Circumstances	B F Installation
Result	Accepted ☒			Rejected ☐	

Name & address of employer's person making and authenticating this report:

Mr. Athif

Declaration: I/We hereby declare that the above information is correct, and the equipment has been thoroughly inspected as far as possible in accordance with manufacturer/standard and found to be free from any apparent defect.

Inspected by

Syed M. Bilal
Equipment Inspector



Approved by

Shahid Javed Muhammad
Technical Manager

