



NATIONAL INSPECTION AND TECHNICAL TESTING COMPANY

CERTIFICATE OF THOROUGH EXAMINATION / LOADTEST

CERTIFICATE NO. : LIC-2025-0236

STICKER NO.: F-WR-000311

DATE OF ISSUE: 26-Oct-2025

Name and Address of the Client	:	SUDHIR COMPANY FOR EQUIPMENTS RENTAL / 32221 Dammam - Additional # 9062		
Work Order No.	:	Fahss-25-329		
Type of Inspection	:			
Location of Inspection	:	Madina		
Type of Equipment	:	SCISSOR LIFT		
Name of Manufacturer / Model Number	:	DINGLI / JCPT0807AC		
Year of Build	:	2024		
Serial Number	:	JPAC024104517		
Owner ID No	:	SD8ESL-1977		
Registration Plate No.	:	N/A		
Motive Power	:	Electrical / hydraulic		
Reference Standard	:	ANSI / SAIA A92.6 / SASO GSO EN 280		
Measuring Equipment ID	:	MEASURING TAPE ID.IIS-00026, VERNIER CALIPER ID.IIS-00001		
DESCRIPTION	Maximum Working Height (m)	Maximum Horizontal Reach (m)	Proof Load Test (KG)	SWL
-Aerial Work Platform type: Scissor lift -on tires -Max.No. of person: 2 - Power : 3 KW -Voltage: 24 V -MEWP Classification: 3A	7.80 Meters	N/A	230 Kg	230 Kg

Inspection Date:	Next inspection Date:	Ref. and Date of Last Inspection
22-Oct-2025	21-Apr-2026	07-Aug-2025

This is to certify that the above **Elevating Work Platform** was tested and thoroughly examined and no defect affecting its safe use was found at the time of inspection. The equipment is **safe to operate** up to its SWL and for its intended use within the design limits specified, provided there is continuous maintenance applied and a qualified operator is employed. This document is valid until the date of next inspection or the date of expiry of thorough examination or the date from which any major repair / alteration is done to the equipment; whichever occurs earlier.

Inspected by: Dia Abdulhamed



Reviewed by: Feroz Hameed

On Behalf of FAHSS

"This document is issued subject to the condition that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, repairer or operator of any warranty, express or implied and National Inspection and Technical Testing Company. (FAHSS) liability shall be limited to the acts or omissions of its employees, agents and sub contractors. FAHSS shall in no event be liable for any injury or damage to any person or property occurring by reason of negligent operation or lack of proper maintenance or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by FAHSS and which are covered under this document."

NATIONAL INSPECTION AND TESTING COMPANY (FAHSS), P.O. Box 3998, DAMMAM 32252, Kingdom of Saudi Arabia
Contacts: +966 (13) 340 7607 | +966 (12) 6109014 | +966 (14) 325 1475 | +966 538400764

EMAIL: info@fahss.com

FAHSS-IIS-LIC-FRM-051 Rev 4. 20/05/2025

ELEVATING WORK PLATFORM INSPECTION CHECKLIST

Owner ID No. / Plate No.	SD8ESL-1977 / N/A	Date	22-Oct-2025
Maker Ser. No.	JPAC024104517	Report No.	LIC-2025-0236

No	Examination Items	S	NS	N/A	Defects Found / Comment
Risk Assessment					
1	Work permit	☒	☐	☐	
2	Inspection area is isolated and safe for inspection and testing	☒	☐	☐	
3	Operator is certified to operate the inspected equipment	☒	☐	☐	
4	Operator informed not to move any part of the equipment unless informed by the inspector for safe operation	☒	☐	☐	
5	Dropped Objects, Overhead Powerlines	☒	☐	☐	
6	Beware of Slips and trips, Rotating machineries	☒	☐	☐	
7	Observe High wind status	☒	☐	☐	
Inspection Checklist					
8	General Condition	☒	☐	☐	
9	Documentations and Certifications	☒	☐	☐	
10	Identification Labels on Controls	☒	☐	☐	
11	Ground Control Console	☒	☐	☐	
12	Platform Control Console	☒	☐	☐	
13	Motion Warning / Reverse Alarm / Horn	☒	☐	☐	
14	Emergency Descending System	☒	☐	☐	
15	Level Indicator	☒	☐	☐	
16	Boom/Jib/ Scissor Structure	☒	☐	☐	
17	Tilting Sensor	☒	☐	☐	
18	Personnel Cage Platform & Anchoring Point	☒	☐	☐	
19	Articulated Jib	☐	☐	☒	
20	Swing Machinery	☐	☐	☒	
21	Turntable Bearing	☐	☐	☒	
22	Overload Limit / Anti Entrapment Device / Safety Devices	☒	☐	☐	
23	Outriggers / Stabilizer	☐	☐	☒	
24	Tires	☒	☐	☐	
25	Brakes	☒	☐	☐	
26	Hydraulic System Hoses	☒	☐	☐	
27	Electrical Integrity	☒	☐	☐	
28	Structural Integrity / Corrosion / Paint work	☒	☐	☐	
29	Maintenance Log	☒	☐	☐	

Note: S= Satisfactory / Accepted | N.S. =Not Satisfactory | N/A = Not Applicable

Inspected by: Dia Abdulhamed




Reviewed by: Feroz Hameed



On Behalf of FAHSS

Reference Standard : ANSI / SAIA A92.6 / SASO GSO EN 280

NATIONAL INSPECTION AND TESTING COMPANY (FAHSS), P.O. Box 3998, DAMMAM 32252, Kingdom of Saudi Arabia

Contacts: +966 (13) 340 7607 | +966 (12) 6109014 | +966 (14) 325 1475 | +966 538400764

EMAIL: Info@fahss.com

FAHSS-IIS-LIC-FRM-049 Rev 3 20/05/2025



NO.: F-WR-000311

EQUIP.NO.: SD8ESL-1977

EQUIP. S.N.: JPAC024104517

DATE INSPECTED: 22-Oct-2025

NEXT INSPECTION DATE: 21-Apr-2026

INSPECTED BY: Dia Abdulhamed