




الشركة العالمية لخدمات التفتيش المحدودة UNIVERSAL INSPECTION CO. LTD.



CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)	
19-May-2025	20-May-2025	DUB-L-0145	DUB/000096	
Next Examination Due Date	Date of last thorough Examination	Reference Standard	Order No	
19-Nov-2025	19-05-2025	BS EN 280-1:2022	W.O-DUB-LIF-20052025-001	
Name and Address of Customer		Address of Examination		
SUDHIR EQUIPMENT RENTAL COMPANY Dubai, Kingdom of Saudi Arabia		GHE Project(Duba), Kingdom of Saudi Arabia		
Description and identification of the equipment		Equipment ID	Safe Working Load	
MANLIFT Battery Powered Articulated Boom Lift Manufacture: Dingli Model: BA16NE, ID No: SE 16 AD-1026 Max. Working Height: 16.30m Max. wind speed: 12.5 m/s Max. Angles: 3°, G.V.W: 6700 Kg M.f.g year: 2024		BAED024A00033	230 Kg 2 persons + 70 kg Eqp.	
Is this first Examination after installation or assembly at new site or location?		NO	Was the Examination carried out within an interval of 6 months?	YES
Has the equipment been installed correctly?		YES	Was the Examination carried out within an interval of 12 months?	NO
In accordance with an Examination Scheme?		NO	After the occurrence of exceptional circumstances?	NO
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:				
N/A				
Is the above an existing or imminent danger to persons?				NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)				NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
N/A				
Particulars of any tests carried out as part of the examination. And standard applied.				
This Battery Powered Articulated Boom Lift has been Visual, Functional Examined in accordance with BS EN 280-1:2022.				
Load Test(s): N/A				
IS THIS EQUIPMENT SAFE TO OPERATE?		YES		
Name and Signature of the person issue this certificate.		Name and Signature of the person authenticating this certificate.		
Name: MUHAMMED SUHAIL.CK		Name: REMON RAJ		
Signature: 		Signature: 		
Comments:				
At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual, maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.				



الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.



Checklist

Certificate/Report Number: DUB-L-0145

Sticker Number(s): DUB/000096

INSPECTION POINTS	Pass	Fail	N/A	INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection Certificate	☒	☐	☐	Air filter	☐	☐	☒
Last Third-party inspection sticker	☒	☐	☐	Steering oil and steering system/Joystick	☒	☐	☐
Operator Iqama/License/ Third Party	☒	☐	☐	Brakes and brake system (including parking brake)	☒	☐	☐
Vehicle documents (Insurance & Estamara)	☒	☐	☐	Fuel level and check for leaks in fuel system	☐	☐	☒
Tire and air pressure	☒	☐	☐	Coolant	☐	☐	☒
Level Indicators	☒	☐	☐	Radiator and hoses	☐	☐	☒
Lights (include beacon light)	☒	☐	☐	Fan belts and pulleys	☐	☐	☒
Horn/ Reverse alarm	☒	☐	☐	Hoses and fittings	☒	☐	☐
Electrical switches and gauges	☒	☐	☐	Battery	☒	☐	☐
Emergency lowering system	☒	☐	☐	Air Conditioner/Heater	☐	☐	☒
Safety signs, labels and stickers	☒	☐	☐	Boom lift, Boom extension & retraction (deflection)	☒	☐	☐
Platform condition	☒	☐	☐	Lever controls & pedals	☒	☐	☐
Greasing & lubrication of boom	☒	☐	☐	Slewing mechanism	☒	☐	☐
Overload Indicator	☒	☐	☐	Boom cylinder/Lifting cylinder	☒	☐	☐
Safe Access & Egress	☒	☐	☐	Pneumatic system	☐	☐	☒
Fire extinguisher in good condition & valid	☒	☐	☐	Identification & SWL Marking	☒	☐	☐
Engine oil level, check system for damage, leak	☐	☐	☒	Hydraulic system	☒	☐	☐
Hydraulic oil level, check system for leaks	☒	☐	☐	Outrigger Jacks	☐	☐	☒
Transmission oil	☒	☐	☐	Operation	☒	☐	☐

Comments/Remarks:

N/A

Reference Documents:

BS EN 280-1:2022.

Inspected & witnessed by: MUHAMMED SUHAIL.CK

Signature:



Approved by: REMON RAJ

Signature: