



## CERTIFICATE OF THOROUGH EXAMINATION

DIESEL GENERATOR

CERTIFICATE / REPORT NO : CRT-199925 R.0

STICKER NO : 155161

JOB NO : WO-54579

DATE OF REPORT : 24/03/2026

EQUIPMENT OWNER : SUDHIR RENTALS  
TYPE OF INSPECTION : PERIODIC VISUAL AND FUNCTIONAL INSPECTIONLOCATION: JIGPC-GIZAN  
DATE OF INSPECTION : 07-Mar-2026  
Frequency 6 month  
Next Inspection Due 06-Sep-2026

EQUIPMENT DESCRIPTION : DIESEL ENGINE POWERED GENERATOR OF RATED CAPACITY 160 KVA

|                                           |                                              |                                              |
|-------------------------------------------|----------------------------------------------|----------------------------------------------|
| MANUFACTURER :<br>VARADA ENERGIES         | MODEL/TYPE :<br>UCI274F1                     | MANUFACTURED YEAR :<br>2024                  |
| SERIAL NO :<br>VEPL/2024-25/194           | OWNER ID :<br>SG-1083-160                    | WORK PROCEDURE NO :<br>SA-WP-06              |
| REFERENCE STANDARDS :<br>ISO 8528-13:2016 | DATE OF PREVIOUS INSPECTION :<br>14-Sep-2025 | PREVIOUS INSPECTION DETAILS:<br>SAICL#138341 |

|                                     |                         |
|-------------------------------------|-------------------------|
| CAPACITY = 160 KVA                  | ENGINE SPEED = 1800 RPM |
| VOLTAGE / FREQUENCY = 380 V / 60 HZ | POWER = 128 KW          |
| NUMBER OF PHASE = 3                 |                         |
| RESULT :<br>SATISFACTORY-PASS       | CHECKLIST NO :<br>96528 |

REMARKS/RECOMMENDATION :  
1. FOLLOW THE PREVENTIVE MAINTENANCE PROCEDURES AS PER MANUFACTURER INSTRUCTIONS TO KEEP THE EQUIPMENT ALWAYS IN GOOD CONDITION.  
2. DO PRE-OPERATIONAL INSPECTION TO ENSURE THE EQUIPMENT IS FREE FROM ANY KIND OF LEAKAGES OR LOOSE CONNECTIONS

Reviewed By : ARIF AL-RASHIDI

Authorised Inspector : ZEIN UL ABEDIN KILLEDAR



SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-199925 R.0 SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-19992  
SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-199925 R.0 SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-19992  
SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-199925 R.0 SERIAL NO: VEPL/2024-25/194 VALID TILL : 06-Sep-2026 Report No: CRT-19992  
Note : This inspection certificate confirms that the inspected equipment comply with the specified requirements as per the inspection criteria.  
However, this document does not constitute a conformity certificate for SABER.

ملحوظة: تؤكد شهادة الفحص هذه أن المعدات التي تم فحصها تتوافق مع المتطلبات المحددة وفقاً لمعايير الفحص. مع ذلك، هذه الوثيقة لا تعتبر شهادة مطابقة لمنصة سابير.

## THIS CERTIFICATE BECOMES INVALID, IF ANY ALTERATION/REPAIR OR MODIFICATION IS MADE TO THE EQUIPMENT

THE CONCERNED INSPECTOR OR REPRESENTATIVE HAS THOROUGHLY EXAMINED THE EQUIPMENT IN ACCORDANCE TO THE RELEVANT STANDARDS. EXAMINATION INDICATES THAT THE SAID EQUIPMENT HAS NO APPARENT DEFECTS OR DEFORMATION WHICH MAY PROVE DANGEROUS DURING NORMAL OPERATION. THE SAID EQUIPMENT IS FOUND TO BE SATISFACTORY FOR FURTHER USE, PROVIDED THERE IS REGULAR MAINTENANCE AND OPERATED BY A CERTIFIED OPERATOR. THIS CERTIFICATE IS GRANTED SUBJECT TO THE CONDITION THAT IS AGREED & UNDERSTOOD THAT STANDARD ARABIA INSPECTION CO. LTD.'S LIABILITY SHALL BE LIMITED TO THE ACTS OF ITS EMPLOYEES ON PREMISES OF SUBCONTRACTORS. UNDER NO CIRCUMSTANCES WHATSOEVER SHALL STANDARD ARABIA INSPECTION CO. LTD. BE LIABLE FOR ANY INJURY OR DAMAGE TO ANY PERSON OR OCCURRING AS A RESULT OF NEGLIGENCE OR ANY DEFECT IN MATERIALS, MACHINERY, EQUIPMENT OR SYSTEMS OTHER THAN DEFECTS ASCERTAINABLE DURING ROUTINE INSPECTION. WE HEREBY REPORT THAT THE ALL PARTICULARS IN THIS REPORT ARE CORRECT AT THE TIME OF TEST / INSPECTION & OPERATIONAL MAINTENANCE IS THE SOLE RESPONSIBILITY OF THE EQUIPMENT OWNER.

THIS CERTIFICATE IS GENERATED AND AUTHORIZED ELECTRONICALLY AND CAN BE CONSIDERED AS ORIGINAL. TO VERIFY THE AUTHENTICITY OF THIS CERTIFICATE, PLEASE SCAN THE QR CODE.

