

NATIONAL INSPECTION AND TECHNICAL TESTING COMPANY

CERTIFICATE OF TEST & EXAMINATION OF FORKLIFT/TELEHANDLER

CERTIFICATE NO. : LIC-2025-0191

STICKER NO.: F-WR-000238

DATE OF ISSUE: 23-Oct-2025

Name and Address of the Client	:	SUDHIR COMPANY FOR EQUIPMENTS RENTAL / 32221 Dammam - Additional # 9062
Work Order No.	:	Fahss-25-365
Type of Inspection	:	Periodic
Location of Inspection	:	USFAN - SUDHIR YARD
Type of Crane	:	TELEHANDLER
Capacity	:	4,540 KG
Name of Manufacturer / Model Number	:	SANY STH1056A5
Year of Build	:	2025
Serial Number	:	TH1056CF0002
Owner ID No	:	STH1056-052
Registration Plate No.	:	N.K
Make & Type of Rated Capacity Indicator	:	SANY
Motive Power	:	DIESEL / HYDRAULIC
Reference Standard	:	ANSI / ITSDF B56.6:2021 , SASO-GSO-5057:1993
Measuring Equipment ID	:	MEASURING TAPE ID NO. IIS-PRE0106127 REPORT . NO. 24-73057 VERNIER CALIPER ID NO. IIS-90193039 REPORT . NO. 24-73047 ANGLE METER ID NO. IIS-PRE0106126, REPORT . NO. 24-73066

DESCRIPTION	HEIGHT (m)	REACH (m)	LOAD CENTER (mm)	TEST LOAD (t)	SWL (t)
TELESCOPIC BOOM ROUGH TERRAIN MATERIAL HANDLER CAPACITY: 4,540 KG @ 2 m LOAD CENTER ENGINE POWER 93 KW MAX LIFTING HEIGHT ON STABILISERS 17,100 MM MAX. REACH ON STABILISERS 12,200 MM CAPACITY (AT MAX. REACH ON STABILISERS) 1,361 KG	0	2	2,000	NIL	4,540

Inspection Date	Next inspection Date	Ref. and Date of Last Thorough Examination	Ref. and Date of Last Proof Load Test	Next Proof Load Test Date
23-Oct-2025	22-Apr-2026	ALLIANCE INFINITE ST. 2029 23-03-25	ALLIANCE INFINITE ST. 2029 23-03-25	AFTER MAJOR REPAIR / MODIFICATION

This is to certify that the above **Forklift/Telehandler** was tested and thoroughly examined and no defect affecting its safe use was found at the time of inspection. The equipment is **safe to operate** up to its SWL and for its intended use within the design limits specified, provided there is continuous maintenance applied and a qualified operator is employed. This document is valid until the date of next inspection or the date of expiry of thorough examination or the date from which any major repair / alteration is done to the equipment; whichever occurs earlier.

Inspected by: Yaser Kahfazan




Reviewed by: Feroz Hameed



On Behalf of FAHSS

"This document is issued subject to the condition that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, repairer or operator of any warranty, express or implied and National Inspection and Technical Testing Company. (FAHSS) liability shall be limited to the acts or omissions of its employees, agents and sub contractors. FAHSS shall in no event be liable for any injury or damage to any person or property occurring by reason of negligent operation or lack of proper maintenance or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by FAHSS and which are covered under this document."

FORKLIFT/TELEHANDLER INSPECTION CHECKLIST

Owner ID No. / Plate No.	STH1056-052 / N.K	Date	23-Oct-2025
Maker Ser. No.	TH1056CF0002	Report No.	LIC-2025-0191

No	Examination Items	S	NS	N/A	Defects Found / Comment
Risk Assessment					
1	Work permit	☒	☐	☐	
2	Inspection area is isolated and safe for inspection and testing	☒	☐	☐	
3	Operator is certified to operate the inspected equipment	☒	☐	☐	
4	Operator informed not to move any part of the equipment unless informed by the inspector for safe operation	☒	☐	☐	
5	Inspection area shall be of strength, level (no more than 1% Grade) and not near Electrical hazards	☒	☐	☐	
6	Beware of Slips and trips, Rotating machineries	☒	☐	☐	
7	Observe High wind status	☒	☐	☐	
Inspection Checklist					
8	General Condition	☒	☐	☐	
9	Documentations, Maintenance and Certifications.	☒	☐	☐	
10	Marking of SWL, Ser.no., Model no.	☒	☐	☐	
11	General Cleanliness and Appearance	☒	☐	☐	
12	Manufacturer Cert. Forks and Chain	☒	☐	☐	
13	Load Chain wear less 8% /Elong less 2%	☐	☐	☒	
14	Connection to load carriage	☒	☐	☐	
15	Pin for wear or elongation	☒	☐	☐	
16	Roller for wear or damage	☐	☐	☒	
17	Hydraulic mast and lines	☐	☐	☒	
18	Hoses and main ram for wear	☒	☐	☐	
19	Main ram seal for any leaks	☒	☐	☐	
20	Mast bearing for wear or damage	☐	☐	☒	
21	Tilt rams operates equally and free of leaks	☐	☐	☒	
22	Carriage structure for wear or damage	☒	☐	☐	
23	Forks for wear, nicks or gouge	☒	☐	☐	
24	Forks for distortion or misalignment	☒	☐	☐	
25	Steering mechanism	☒	☐	☐	
26	Foot brake operation	☒	☐	☐	
27	Handbrake operation	☒	☐	☐	
28	Electrical system	☒	☐	☐	
29	Counterweights	☒	☐	☐	
30	Wheel tires for damage or significant wear	☒	☐	☐	

Note: S= Satisfactory / Accepted | N.S. =Not Satisfactory | N/A = Not Applicable

Inspected by: Yaser Kahfazan




Reviewed by: Feroz Hameed



On Behalf of FAHSS

Reference Standard : ANSI / ITSDF B56.6:2021 , SASO-GSO-5057:1993

NATIONAL INSPECTION AND TESTING COMPANY (FAHSS), P.O. Box 3998, DAMMAM 32252, Kingdom of Saudi Arabia

Contacts: +966 (13) 340 7607 | +966 (12) 6109014 | +966 (14) 325 1475 | +966 538400764

EMAIL: info@fahss.com

FAHSS-IIS-LIC-FRM-062 Rev 3 20/05/2025



NO.: F-WR-000238

EQUIP.NO.: STH1056-052

EQUIP. S.N.: TH1056CF0002

DATE INSPECTED: 23-Oct-2025

NEXT INSPECTION DATE: 22-Apr-2026

INSPECTED BY: Yaser Kahfazan