



## Certificate of Insurance

Policy Holder Name  
Policy Number  
Original Policy Period

Sudhir Equipment Rental Company  
5/EP/30425/0/0  
05/04/2026 to 04/04/2027

اسم حامل الوثيقة  
رقم الوثيقة  
فترة الوثيقة الأصلية

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والآلات المقاولين للمعدة المذكورة أدناه، وذلك وفقا لشروط وثيقة التأمين المذكورة أعلاه:

|                          |   |               |   |                       |
|--------------------------|---|---------------|---|-----------------------|
| Asset ID                 | : | S20AD-2121    | : | معرف الأصل            |
| Brand                    | : | DINGLI        | : | العلامة التجارية      |
| Type                     | : | BA20CRT2      | : | النوع                 |
| Model                    | : | AWPS          | : | الطرز                 |
| Manufacturing Year       | : | 2025          | : | سنة الصنع             |
| Equipment Serial Number  | : | BARC024K00707 | : | الرقم التسلسلي للمعدة |
| Purchase Value           | : | 161250        | : | قيمة الشراء           |
| Insurance Effective Date | : | 05/04/2026    | : | تاريخ سريان التأمين   |

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تم اصدار هذه الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة

Al Khobar : 01<sup>st</sup> April 2026

Signature of Insurer's Authorized Representative



PUBLIC

### Gulf Insurance Group

A Saudi joint stock company | Paid-up capital 500 Million Saudi Riyals  
Licensed by No (TMN/25/20101) | Commercial Registration No.1010271203  
3528 King Abdullah Bin Abdulaziz Road, Al Nuzha District  
Unit No. 25 | Riyadh 12471 - 6378  
Toll free 8001160020 | Website [www.gig.sa](http://www.gig.sa)  
Regulated and Supervised by The Saudi Central Bank

### مجموعة الخليج للتأمين

شركة مساهمة سعودية | رأس المال 500,000,000 ريال سعودي  
مرخص لها برقم ترخيص (ت م ن/25/20101) | سجل تجاري رقم 1010271203  
3528 طريق الملك عبدالله بن عبدالعزيز، حي النزهة  
رقم الوحدة 25 | الرياض 12471 - 6378  
[www.gig.sa](http://www.gig.sa) الرقم المجاني 8001160020 | الموقع الإلكتروني  
خاضعة لرقابة وإشراف البنك المركزي السعودي

## OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

|                           |                                |
|---------------------------|--------------------------------|
| <b>Equipment</b>          | <b>AWP</b>                     |
| <b>Brand / Make</b>       | <b>DINGLI</b>                  |
| <b>Asset ID</b>           | <b>S20AD-2121</b>              |
| <b>Model Number</b>       | <b>BA20CRT2</b>                |
| <b>Serial Number</b>      | <b>BARC024K00707</b>           |
| <b>Working Height</b>     | <b>20 Meter</b>                |
| <b>Type</b>               | <b>Diesel Articulated Boom</b> |
| <b>Manufacturing Year</b> | <b>2025</b>                    |

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : [Info@sudhirrentals.com](mailto:Info@sudhirrentals.com)

Sincerely,

Ajay Koul  
General Manager  
Sudhir Equipment Rental Company





## REGISTERED CERTIFICATE OF LOAD TEST & THOROUGH EXAMINATION OF A MOBILE ELEVATING WORK PLATFORM

Time Sheet No: **07393 /JO-5330**

Sticker No: **11865**

Certificate No: **AI-CERT-MMA-294**

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                    |                                                                                                                             |                                         |                         |                            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|-------------------------|----------------------------|
| Name & Address of the Owner of the MEWP<br><b>SUDHIR EQUIPMENT RENTALS, KSA</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                    | Date of Inspection<br><b>13/07/2025</b>                                                                                     |                                         |                         |                            |
| Name & Address of the Maker of the MEWP<br><b>ZHEJIANG DINGLI</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                                    | Location of Inspection<br><b>CEER PROJECT RABIGH, KSA</b>                                                                   |                                         |                         |                            |
| Type of MEWP<br><b>Diesel Powered Type Mounted Articulating Boom Mobile Elevating Work Platform Manlift</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |                                                    | Rel. Standard<br><b>BS EN 280-2013-A1-2015, BS 8460-2005 Procedure NO.: AI-IP-041, SASO GSO EN 280</b>                      |                                         |                         |                            |
| Date of Previous Inspection:<br><b>NA</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |                                                    | Date of Previous Load test:<br><b>NA</b>                                                                                    |                                         |                         |                            |
| Date of Manufacture of MEWP<br><b>2025</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         | Maker's Serial No of MEWP.<br><b>BARC024K00707</b> | Model No.:<br><b>BA20CRT2</b>                                                                                               | Owner's ID/Reg No:<br><b>S20AD-2121</b> |                         |                            |
| <p>In the case of the MEWP with variable operating radius, the safe working load at various radii shall be given. Test loads at various radii should be given in column (iii) and in the case of a safe working which has been calculated without the application of a test load, "NIL" should be entered in that column.</p> <p>2200 lbs = 1 Tonne</p> <p>➤ <b>Max Working Height : 20.15 Mtr</b></p> <p>➤ <b>Max Platform Height : 18.15 Mtr</b></p> <p>➤ <b>Max Horizontal Reach : 11.13 Mtr</b></p> <p>➤ <b>Gradeability : 45 %</b></p> <p>➤ <b>Max Slope: 5.0°</b></p> <p><b>Next Examination Due: 12-01-2026</b> Or after any repair or Alteration of the Manlift Configuration.</p> <p><b>Next Test Due: 12-01-2026</b> Or after any repair or Alteration of the Manlift Configuration.</p> |                                                    | (i)<br>Length of Boom<br>(m)                                                                                                | (ii)<br>Radius<br>(m)                   | (iii)<br>Test Load (Kg) | (iv)<br>S.W.L.<br>(Kg)     |
|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                    | <b>18.15 Mtr Platform Height</b>                                                                                            | <b>All Radil</b>                        | <b>320 kg</b>           | <b>320 kg (2P + Tools)</b> |
| <p><b>Remarks:</b></p> <ul style="list-style-type: none"> <li>The operator SHALL properly inspect the above-mentioned equipment for any relevant defects or performance malfunctioning in daily bases and ensure that emergency lowering system is functional.</li> <li>Only a qualified and certified operator shall operate the MEWP</li> <li>Manufacturer instruction SHALL be followed.</li> <li>Certificate will be null and void, in case of any alteration or/and major repair.</li> </ul>                                                                                                                                                                                                                                                                                                  |                                                    |                                                                                                                             |                                         |                         |                            |
| Equipment used:<br><b>N.A.</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |                                                    | Equipment was found <b><u>SATISFACTORY</u></b> at the time of examination.                                                  |                                         |                         |                            |
| In the case of a MEWP with a derricking jib or jibs, the maximum angle at which the jib may be worked.<br><b>N.A.</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                                    | Defects noted and alterations or repairs required before the MEWP is put into service (if none enter 'NONE')<br><b>NONE</b> |                                         |                         |                            |

**Head Office Address:**

ALLIANCE INFINITE LLC 5900 BALCONES DRIVE STE 4147 AUSTIN TEXAS 78731 USA  
T: +1 979-328-1759  
E: info@allianceinfinite.com  
W: www.allianceinfinite.com  
Bahrain Office Address:  
Gems Tower, Hidd, Bahrain  
KSA Office:  
Al Mergab Tower, 9<sup>th</sup> floor 9b, Jubail, KSA  
AI/1252/12/REV.01 - 01/10/1998 ©  
TECHUVI/1252/12/REV.01 - 01/10/1998 ©



**Liability** – the client or his assignee or supervisor in interest agrees to indemnify and hold harmless Alliance Infinite from and against any claims, demands, lawsuits, or actions for damages, including legal fees to persons and/or property tangible, intangible or otherwise which may be brought against Alliance Infinite incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of Alliance Infinite's directors, officers, employees or sub-contractors.

Under no circumstances whatsoever shall Alliance Infinite be liable for any injury or damage to any person or property occurring because of any defect in all design, materials, machinery, equipment or other items which it is the responsibility of Alliance Infinite to inspect under the terms specified hereunder. Nothing herein contained shall be deemed to relieve any seller, or manufacturer of its warranties, express or implied.

In the event, Alliance Infinite's proven negligent in any respect, the liability of, Alliance Infinite agents, employees, and subcontractors for proprietors' claims shall not exceed the greater of US\$ 1,000 or five (5) times the total compensation paid to Alliance Infinite for the work. The proprietor shall save, defend and hold Alliance Infinite harmless against more than US \$ 1,000 or five (5) times the total compensation paid to Alliance Infinite LLC and Group of companies

|        |      |                 |              |        |
|--------|------|-----------------|--------------|--------|
| Author | Rev. | Date of Release | Document ID. | Page   |
| MR     | 00   | 01.01.2024      | AI-IC-05     | 1 of 2 |



**CHECKLIST FOR MOBILE ELEVATING WORK PLATFORM**

Time Sheet No: **07393 /JO-5330**

Sticker No: **11865**

Certificate No: **AI-CERT-MMA-294**

| SECTION                       | NEEDED CORRECTIONS<br>(if any) DEFECTS NOTED | CLEARANCE |         |
|-------------------------------|----------------------------------------------|-----------|---------|
|                               |                                              | DATE      | INITIAL |
| Duty Chart / Operation Manual | Satisfactory                                 |           |         |
| ID on Controls / Panel        | Satisfactory                                 |           |         |
| Boom Sections                 | Satisfactory                                 |           |         |
| Personnel Platform            | Satisfactory                                 |           |         |
| Hydraulic System              | Satisfactory                                 |           |         |
| Main Hydraulic Motor          | Satisfactory                                 |           |         |
| Swing Machinery               | Satisfactory                                 |           |         |
| Turntable Bearing             | Satisfactory                                 |           |         |
| Tyres                         | Satisfactory                                 |           |         |
| Electrics                     | Satisfactory                                 |           |         |
| Horn / Motion Audible Alarm   | Satisfactory                                 |           |         |
| D.C. Motor Unit – Carrier     | Satisfactory                                 |           |         |
| Ground / Platform Controls    | Satisfactory                                 |           |         |
| Power Train                   | Satisfactory                                 |           |         |
| Safety System / Markings      | Satisfactory                                 |           |         |
| Fire Extinguishers            | Satisfactory                                 |           |         |
| Maintenance                   | Satisfactory                                 |           |         |
| General Condition             | Satisfactory                                 |           |         |

**THIS IS TO CERTIFY THAT** the Undersigned, a competent inspector, did, attend the MEWP site to examine by surface inspection and witness testing to ascertain that this MEWP, its machinery, gears, lifting appliances, structural supports/fixtures and associate apparatus have withstood the load testing, if herein applied, without injury or permanent deformation to the MEWP. This MEWP is safe for its intended use within the limits specified providing there is continuous maintenance applied and qualified operators employed.

Issue Date: **13-07-2025**



Inspected by : **Mohd Murshid Alam**  
Inspection Engineer

*Murshid*

Approved **MOHAMED RIYAZ KHAN**  
Authorized Signatory

**Head Office Address:**

ALLIANCE INFINITE LLC 5900 BALCONES DRIVE STE 4147 AUSTIN TEXAS 78731 USA  
T: +1 979-328-1759  
E: info@allianceinfinite.com  
W: www.allianceinfinite.com  
Bahrain Office Address:  
Gems Tower, Hidd, Bahrain  
KSA Office:  
Al Mergab Tower, 9<sup>th</sup> floor 9b, Jubail, KSA  
AI/1252/12/REV.01 – 01/10/1998 ©  
TECHUVI/1252/12/REV.01 – 01/10/1998 ©



**Liability** – the client or his assignee or supervisor in interest agrees to indemnify and hold harmless Alliance Infinite from and against any claims, demands, lawsuits, or actions for damages, including legal fees to persons and/or property tangible, intangible or otherwise which may be brought against Alliance Infinite incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of Alliance Infinite's directors, officers, employees or sub-contractors.

Under no circumstances whatsoever shall Alliance Infinite be liable for any injury or damage to any person or property occurring because of any defect in all design, materials, machinery, equipment or other items which it is the responsibility of Alliance Infinite to inspect under the terms specified hereunder. Nothing herein contained shall be deemed to relieve any seller, or manufacturer of its warranties, express or implied.

In the event, Alliance Infinite's proven negligent in any respect, the liability of, Alliance Infinite agents, employees, and subcontractors for proprietors' claims shall not exceed the greater of US\$ 1,000 or five (5) times the total compensation paid to Alliance Infinite for the work. The proprietor shall save, defend and hold Alliance Infinite harmless against more than US \$ 1,000 or five (5) times the total compensation paid to Alliance Infinite LLC and Group of companies

| Author | Rev. | Date of Release | Document ID. | Page   |
|--------|------|-----------------|--------------|--------|
| MR     | 00   | 01.01.2024      | AI-IC-05     | 2 of 2 |



Sticker No.:  
**BV-3966**

**BUREAU VERITAS**

Tel: +966 13 882 1071

Fax: +966 13 882 1072

Al Khobar, Saudi Arabia



**BUREAU  
VERITAS**

EQUIP. S.N.:

**BARC024K00707**

EQUIP. NO.:

**S20AD-2121**

EQUIP. SWL:

**320 KG**

INSPECTION DATE:

**JAN 13, 2026**

NEXT INSPECTION DATE:

**JULY 12, 2026**

INSPECTOR NAME:

**M. Al-Mahmoud**

SAP #:

**80019106**

"S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY"



## Bureau Veritas, Saudi Arabia

8th Floor, Danah Business Tower, Olaya District, Al Khobar, Kingdom of Saudi Arabia

Tel No : +966 13 882 1071

Web : <https://middle-east.bureauveritas.com>



Report No.: 248209

|                                                        |                                |                                |              |                                          |                                       |                   |
|--------------------------------------------------------|--------------------------------|--------------------------------|--------------|------------------------------------------|---------------------------------------|-------------------|
| LIFTING EQUIPMENT<br>INSPECTION REPORT                 | RPO NO. N/A                    |                                |              | CRM NO. -                                | Report No. 248209                     |                   |
|                                                        | Area<br>DAMMAM                 | Inspection Date<br>13/01/2026  |              | Inspection Time<br>14:00                 | Previous Sticker                      |                   |
|                                                        |                                |                                |              |                                          | No.FAHSS 006856                       | Issue By TUV NORD |
| Department / Contractor<br>SUDHIR EQUIPMENT RNETAL CO. | Equipment Number<br>S20AD-2121 | Equipment Location<br>DMM YARD |              | Inspection Result<br>Pass                | New Sticker No.<br>BV-3966            |                   |
| Manufacturer<br>DINGLI                                 | Model<br>BA20CRT2              | Capacity<br>320 KG             | Type<br>MEWP | Equipment Serial Number<br>BARC024K00707 | Sticker Expiration Date<br>12/07/2026 |                   |

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's, ASME and API Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

| No. | DEFICIENCIES / NOTES                                                                                                                                                                                                         | Corrective Action Taken |
|-----|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1   | -PERIODIC INSPECTION AND FUNCTION TEST FOR BOOM SUPPORTED ELEVATING WORK PLATFORM<br>AS PER AS S.ARAMCO GI 7.030 AND ANSI 92.5<br>-EQUIPMENT WAS FOUND SATISFACTORY AT THE TIME OF INSPECTION<br>-FOLLOW PROPER PM REGULARLY | -                       |

|                                    |                                                                                                                    |                                                                                                                                                |                                                                                                                         |
|------------------------------------|--------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| <b>Receiver's Name :</b><br>ASHISH | <b>Badge No :</b><br>-                                                                                             | <b>Technical Reviewer Name :</b><br>MAHMOUD EL NAHAS<br><b>Received Date:</b> 13/01/2026                                                       | <b>Inspector Name :</b><br>MOHAMED OMARA                                                                                |
| <b>Telephone No:</b> 055 441 2746  | <b>Receiver Signature :</b><br> | <b>Signature:</b><br><b>Reviewed Date:</b> 13/01/2026<br> | <b>Inspector's Signature :</b><br> |

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

|                                               |                                      |                       |                                                  |                                                           |                                                  |
|-----------------------------------------------|--------------------------------------|-----------------------|--------------------------------------------------|-----------------------------------------------------------|--------------------------------------------------|
| <b>SAUDI ARAMCO INSPECTION CHECKLIST</b>      |                                      |                       | SAIC NUMBER<br><b>SAIC-U-7013</b>                | ISSUE DATE<br><b>12-Jan-23</b>                            | DISCIPLINE<br><b>ELEVATING/LIFTING EQUIPMENT</b> |
| <b>BOOM SUPPORTED ELEVATING WORK PLATFORM</b> |                                      |                       |                                                  |                                                           |                                                  |
| PROJECT TITLE                                 |                                      |                       | WBS/BI/JO NUMBER                                 | INSPECTION COMPANY<br><b>Bureau Veritas, Saudi Arabia</b> |                                                  |
| EQUIPMENT ID NUMBER :<br>S20AD-2121           | EQUIPMENT DESCRIPTION/TYPE :<br>MEWP |                       | SERIAL NO. :<br>BARC024K00707                    | REPORT No.: 248209                                        |                                                  |
| CAPACITY (SWL) :<br>320 KG                    | MANUFACTURER :<br>DINGLI             |                       | FACILITY / LOCATION :<br>DMM YARD                |                                                           |                                                  |
| REQUESTED INSPECTION DATE :                   | RFI No.                              | TASK COMPLETED DATE : | EQUIPMENT OWNER :<br>SUDHIR EQUIPMENT RNETAL CO. |                                                           |                                                  |

## ACCEPTANCE CRITERIA

### 1. GENERAL REQUIREMENTS

|     |                                                                                                                              | REFERENCE                   | PASS | FAIL | NA | REMARKS |
|-----|------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------|------|----|---------|
| 1.1 | Equipment documentation is available                                                                                         | ANSI/SAIA A92.5, G.I. 7.030 | ✓    |      |    |         |
| 1.2 | Previous inspection reports are checked                                                                                      | ANSI/SAIA A92.5, G.I. 7.030 | ✓    |      |    |         |
| 1.3 | Daily pre-operational inspection checklists are checked (if applicable)                                                      | ANSI/SAIA A92.5, Sec: 6.4.1 | ✓    |      |    |         |
| 1.4 | Preventive Maintenance is established and updated records are maintained                                                     | ANSI/SAIA A92.5, Sec: 6.4.1 | ✓    |      |    |         |
| 1.5 | Equipment is operated by a qualified operator                                                                                | ANSI/SAIA A92.5             | ✓    |      |    |         |
| 1.6 | Warning notice, cautions or restrictions for safe operation and maintenance are clearly displayed and legible                | ANSI/SAIA A92.5             | ✓    |      |    |         |
| 1.7 | A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice | G.I. 7.030                  | ✓    |      |    |         |
| 1.8 | Manufacturer name, address, serial number and model are clearly marked or tagged                                             | ANSI/SAIA A92.5             | ✓    |      |    |         |

|      |                                                                                 | REFERENCE                  | PASS | FAIL | NA | REMARKS |
|------|---------------------------------------------------------------------------------|----------------------------|------|------|----|---------|
| 1.9  | Safe working load and number of persons are clearly marked on the work platform | ANSI/SAIA A92.5, SAES-B067 | ✓    |      |    |         |
| 1.10 | Maximum platform height and reach are clearly marked                            | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 1.11 | Maximum travel height and travel directions are clearly marked                  | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 1.12 | Power rating are provided and marked (for AC and/or DC)                         | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 1.13 | Platform and guardrails electrical insulation data are provided                 | GI 7.030 Para: 5.1.2       |      |      | ✓  |         |

## 2. INSPECTION POINTS

|     |                                                                                                     | REFERENCE       | PASS | FAIL | NA | REMARKS |
|-----|-----------------------------------------------------------------------------------------------------|-----------------|------|------|----|---------|
| 2.1 | Platform surfaces are at least 18" (width & length) and are slip-resestant                          | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.2 | Platform guardrails are provided and secure                                                         | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.3 | Platform guardrails are 42" height (+/- 3")                                                         | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.4 | Platform toeboard is fitted and at least 4" high                                                    | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.5 | Moving parts are guarded                                                                            | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.6 | Personnel on the platform is protected against the hazards of moving parts of the aerial platforms. | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.7 | Access to the platform is provided                                                                  | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.8 | Access gates or openings shall be properly closed per the manufacturer's instructions               | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.9 | Electrical cables, wiring and components are undamaged                                              | ANSI/SAIA A92.5 | ✓    |      |    |         |

|      |                                                                                             | REFERENCE       | PASS | FAIL | NA | REMARKS |
|------|---------------------------------------------------------------------------------------------|-----------------|------|------|----|---------|
| 2.10 | Safety harness anchorage is fitted in the platform                                          | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.11 | Battery is secure, guarded and ventilated                                                   | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.12 | Outrigger position microswitches and interlocks are fully functional at their contril panel | ANSI/SAIA A92.5 |      |      | ✓  |         |
| 2.13 | Air, Hydraulic and fuel systems are not leaking                                             | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.14 | Emergency stop button is available at ground control station                                | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.15 | There are no loose nuts, bolts, missing, worn or damaged parts around the structure         | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.16 | The equipment is free of defective and/or corroded members/joints                           | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.17 | Working environment is hazard free and machine ca be safely operated                        | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.18 | An hour meter is fitted                                                                     | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.19 | A fire extinguisher is fitted (type depends on operating location)                          | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.20 | All moving parts are lubricated                                                             | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.21 | All fluid levels for oil, water and hydraulic are adequate                                  | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.22 | Platform controls operate the machine correctly                                             | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.23 | Platform controls are clearly marked with direction and mode of operation                   | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.24 | Platform controls accessable to the operator                                                | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.25 | Platform controls return to "off" or "neutral" position when released                       | ANSI/SAIA A92.5 | ✓    |      |    |         |
| 2.26 | Platform controls are protected agains inadvertent operation                                | ANSI/SAIA A92.5 | ✓    |      |    |         |

|      |                                                                                                                         | REFERENCE                  | PASS | FAIL | NA | REMARKS |
|------|-------------------------------------------------------------------------------------------------------------------------|----------------------------|------|------|----|---------|
| 2.27 | Over-ride control for power functions is fitted at ground level control panel                                           | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.28 | Lower controls return to "off" or "neutral" position when released                                                      | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.29 | Lower controls are clearly marked for direction and mode of operation                                                   | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.30 | Lower controls do not include drive and steering functions                                                              | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.31 | Lower controls are protected against inadvertent operation                                                              | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.32 | Boom raise/extend is operable from platform and ground control                                                          | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.33 | Boom lower/retract is operable from platform and ground control                                                         | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.34 | Platform rotation is operable from both platform and ground controls                                                    | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.35 | Emergency stop button is operable from both platform and ground controls                                                | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.36 | Auxiliary/emergency lowering is operable from platform and ground controls                                              | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.37 | Auxiliary/emergency retracting is operable from platform and ground controls                                            | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.38 | Auxiliary/emergency rotating is operable from platform and ground controls                                              | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.39 | Hydraulic/Pneumatic systems are leak-free with platform raised                                                          | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.40 | Tilt alarm is operable (5 degrees out of level) (manually depress the edge of the tilt switch to cause alarm condition) | ANSI/SAIA A92.5 Sec: 4.6.6 | ✓    |      |    |         |

|      |                                                                                                                                                    | REFERENCE                  | PASS | FAIL | NA | REMARKS |
|------|----------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|------|------|----|---------|
| 2.41 | Aerial platforms is fitted with a warning device at the platform which activates automatically when the aerial platform is at and beyond the slope | ANSI/SAIA A92.5 Sec: 4.6.6 | ✓    |      |    |         |
| 2.42 | Tilt alarm is not combined with boom raise cut-out (dependent on machine manufacturer)                                                             | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.43 | Steering is properly working when moving forward and in reverse directions                                                                         | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.44 | Brakes are in good working condition and can hold the machine on any slope (parking and moving)                                                    | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.45 | Extendable axles function is satisfactory (where fitted)                                                                                           | ANSI/SAIA A92.5            |      |      | ✓  |         |
| 2.46 | Outriggers (stabilizers) extension-retraction operation is satisfactory                                                                            | ANSI/SAIA A92.5            |      |      | ✓  |         |
| 2.47 | Extendable elevating assembly operation is satisfactory (retracted vs. extended)                                                                   | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.48 | Elevating assembly operation is satisfactory (elevated vs. lowered)                                                                                | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.49 | Wheels and tyres are serviceable and undamaged                                                                                                     | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.50 | Travel alarm is operable                                                                                                                           | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.51 | Platform lowering alarm is operable                                                                                                                | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.52 | Auxiliary power source is available (ready to be used in event of primary power loss)                                                              | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.53 | Machine is safely drivable from the platform when raised (fast, slow, forward and reverse modes)                                                   | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.54 | The platform does not descend when in raised position and the power is off                                                                         | ANSI/SAIA A92.5            | ✓    |      |    |         |
| 2.55 | Engine powered machines fuel lines are supported to minimize chafing                                                                               | ANSI/SAIA A92.5            | ✓    |      |    |         |

|      |                                                                                                   | REFERENCE                 | PASS | FAIL | NA | REMARKS |
|------|---------------------------------------------------------------------------------------------------|---------------------------|------|------|----|---------|
| 2.56 | Engine powered machines fuel lines are positioned to minimize exposure to engine and exhaust heat | ANSI/SAIA A92.5           | ✓    |      |    |         |
| 2.57 | Engine powered machines exhaust system is provided with muffler                                   | ANSI/SAIA A92.5           | ✓    |      |    |         |
| 2.58 | Installation of Anti- Entrapment device on work platform                                          | Letter No. CIU-L-019/2016 | ✓    |      |    |         |

## REMARKS

-

This check list will be applied for Vehicle Mounted Elevating Work Platform - ANSI/SAIA A92.2.

- Inspected equipment with refrence to ANSI/SAIA A92.5 shall be equipped with Anti- Entrapment device on work platform.

### REFERENCE DOCUMENTS:

- 1- ANSI/SAIA A92.5 - 2014 Issue: Boom - Supported Elevating Work Platforms
- 2- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 3- SA GI 7.025 -2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 4- SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

## Signature

Inspected / Witnessed by 3rd Party Certified Inspector

**Name** MOHAMED OMARA

**Signature**

**Certificate No.** 80019106

**Company** Bureau Veritas

**Telephone No** 055 078 7628

## User Representative

**Name** ASHISH

**Signature**



**Date** 13/01/2026

**Badge** -

**Telephone No:** 055 441 2746



**Sticker  
No:  
BV-3966**

**Bureau  
Veritas**  
Tel.: + 966 013  
822 1071  
Fax: + 966 013  
822 1072  
Al Khobar,  
Saudi Arabia



**EQUIP .S.N: BARC024K00707**

**EQUIP .NO : S20AD-2121**

**EQUIP.SWL : 320 KG**

**INSPECTION DATE : 13/01/2026**

**NEXT INSPECTION DATE :12/07/2026**

**INSPECTOR NAME: MOHAMED OMARA**

**SAP # 80019106**

**SA INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY**

## Client Satisfaction and Service Feedback

### Survey questions

|   |                                                                                                   | Answers | Remarks |
|---|---------------------------------------------------------------------------------------------------|---------|---------|
| 1 | Did the Service provider Co. provide the right inspector with a valid qualification card?         | Yes     |         |
| 2 | Did the service provider Co. respond for inspection within the expected time frame?               | Yes     |         |
| 3 | Was the inspector wearing the required personal protective equipment (PPE) during the inspection? | Yes     |         |
| 4 | Did the inspection conducted safely and in accordance with Aramco's standards?                    | Yes     |         |

For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)