

Ownership Certificate

To Whom It May Concern

This is to certify that the following equipment mentioned below are the sole owned by **Sudhir Equipment Rental Company**.

Equipment	Boom Lift
Brand / Make	JLG
Asset ID	S26AJ-447
Model Number	800AJ
Serial Number	0300239619
Working Height	26 Meter
Type	Articulated
Manufacturing Year	2017

Mansoor Ali
Branch Manager
Sudhir Equipment Rental Company
Dammam- KSA





Certificate of Insurance

Policy Holder Name
Policy Number
Original Policy Period

Sudhir Equipment Rental Company
5/EP/30425/0/0
05/04/2026 to 04/04/2027

اسم حامل الوثيقة
رقم الوثيقة
فترة الوثيقة الأصلية

Gulf Insurance Group certifies that above client is holding Contractor's Plant & Machinery Insurance Policy for the below mentioned Equipment in accordance with the above mentioned Insurance Policy:

تشهد مجموعة الخليج للتأمين بأن العميل المذكور أعلاه يحمل وثيقة تأمين على معدات والآلات المقاولين للمعدة المذكورة أدناه، وذلك وفقاً لشروط وثيقة التأمين المذكورة أعلاه:

Asset ID : S26AJ-447
Brand : JLG
Type : 800AJ
Model : AWPS
Manufacturing Year : 0
Equipment Serial Number : 300239619
Insurance Effective Date : 05/04/2026

معرف الأصل
العلامة التجارية
النوع
الطراز
سنة الصنع
الرقم التسلسلي للمعدة
تاريخ سريان التأمين

This Certificate has been issued upon Insureds request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تم اصدار هذه الشهادة بناء على طلب المؤمن له وذلك حسب الشروط والاستثناءات والاشتراطات المذكورة في الوثيقة

Al Khobar : 01st April 2026

Signature of Insurer's Authorized Representative



PUBLIC

Gulf Insurance Group

A Saudi joint stock company | Paid-up capital 500 Million Saudi Riyals
Licensed by No (TMN/25/20101) | Commercial Registration No.1010271203
3528 King Abdullah Bin Abdulaziz Road, Al Nuzha District
Unit No. 25 | Riyadh 12471 - 6378
Toll free 8001160020 | Website www.gig.sa
Regulated and Supervised by The Saudi Central Bank

مجموعة الخليج للتأمين

شركة مساهمة سعودية | رأس المال 500,000,000 ريال سعودي
مرخص لها برقم ترخيص (ت م ن/25/20101) | سجل تجاري رقم 1010271203
3528 طريق الملك عبدالعزيز بن عبدالعزيز، حي النزهة
رقم الوحدة 25 | الرياض 12471 - 6378
www.gig.sa الرقم المجاني 8001160020 | الموقع الإلكتروني
خاضعة لرقابة وإشراف البنك المركزي السعودي



**MANLIFT
ENGINEERING CORNER FOR
INSPECTION COMPANY LTD.**



ECI.109092

Capacity : 500 LBS

Equipment No. : S26AJ-447

Serial No. : 0300239619

Inspected Date : 02-MAY-26

Next Inspection : 01-NOV-26

Inspector : BARICK

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address: eci@eccgroupksa.com



REPORT OF A THOROUGH EXAMINATION

Issue Date: 04-May-2026

Certificate Number: ECI/SA/C-01180/26 Rev. No: 00	Report Number: 131576	Sticker Number: 109092
Date of Thorough Examination: 02-May-2026	Date of Expiration: 01-Nov-2026	S.O.#: DMM/05-26/001 Ref.#: N/A

Client: SUDHIR EQUIPMENT RENTAL COMPANY	Address of Premises at Which the Examination Was Made: DAMMAM
---	---

Description and Identification of the Equipment:	Load Test Detail	Safe Working Load(s)	Applied Load(s)
Equipment / Type : MOBILE ELEVATING WORK PLATFORM / BOOM SUPPORTED - MANLIFT	N/A	500 LBS	N/A
Location of the Equipment : DAMMAM YARD			
Equipment ID No : S26AJ-447			
Equipment Serial No : 0300239619			
Model : 800AJ			
Manufacturer / Date of Manufacture : JLG / 2018			
Applied Standard : SASO-ISO-18893 : 2014 & ANSI/SAIA A92.5 : 2006(2014)			

Examination after installation / In-Services	Was the Examination carried out Within an interval of
☐ Initial ☒ Periodic Inspection ☐ Re-Inspection after Major Repair / Modification Or Overhaul	☐ 3 Months ☒ 6 Months ☐ 12 Months ☐ After the exceptional circumstances
Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment.	
Description of the Load Test : N/A	
Pre Load Test NDT done by : N/A	% of Load Applied : N/A
Post Load Test NDT done by : N/A	Expiration of Load Test : N/A
Result	PASS ☒ FAIL ☐
Is the above a defect which is of immediate danger to persons?	YES ☐ NO ☒
Is the above a defect which is not yet but could become a danger to persons?	YES by : ☐ NO ☒
Particulars of any repair, renewal or alteration required to remedy the defect identified above: N/A	
Is this equipment safe to operate?	YES ☒ NO ☐

Note: We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

Liability: The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

Inspected by: MOHAMED ABDUL BARICK	Approved & Reviewed By: UMER ALI KHAN	QR Code:
Signature:		

	Engineering Corner for Inspection Company Limited INSPECTION CHECKLIST Mobile Elevating Work Platform	Doc. No.	ECIR - LFT - 109
		Rev. No.	02
		Rev. Date	17-FEB-2026
		Page No.	2 of 4

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	SUDHIR EQUIPMENT RENTAL COMPANY /	Report No. & Date	131576 02-May-2026
Manufacturer / Year	JLG / 2018	Location	DAMMAM YARD
Type / Model	MOBILE ELEVATING WORK PLATFORM / BOOM SUPPORTED - MANLIFT / 800AJ	Equipment ID. No.	S26AJ-447
Inspection Date	02-May-2026	Equipment Sr. No.	0300239619
Inspector Name	MOHAMED ABDUL BARICK	Capacity / SWL	500 LBS
Standard	SAS-ISO-18893:2014	Expiration Date	01-Nov-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
DOCUMENTATION & RECORDS					5.1	Wiring harness: No frayed wires, loose connections, or chafing.	☒		
1.1	Previous Inspection report	☒			5.2	Battery: Terminals clean and tight; fluid level correct; no corrosion.	☒		
1.2	Operator's manual (handbook) is present and legible.	☒			5.3	Limit switches and sensors: Present, securely mounted, and appear functional.	☒		
1.3	Maintenance and inspection records are available and up-to-date.	☒			POWER UNIT & DRIVE				
1.4	All decals, warnings, and control markings are in place and legible.	☒			6.1	Engine/Motor: Fluids correct (oil, coolant, fuel).	☒		
1.5	Manufacturer's safety bulletins have been checked and complied with (if applicable).	☒			6.2	Fuel system: No leaks.	☒		
STRUCTURAL INTEGRITY					6.3	Brakes: Function properly (including parking brake).	☒		
2.1	Chassis and frame: No visible cracks, deformation, or damage.	☒			6.4	Steering: Operates smoothly with no excessive play.	☒		
2.2	Extending structure (boom, mast, scissors): No cracks, distortion, or weld damage.	☒			6.5	Wheels and tires: Proper inflation (if pneumatic), no damage.	☒		
2.3	Work platform floor: Clean, no holes, anti-skid surface intact.	☒			6.6	Wheel nuts/fasteners: Torqued properly and present.	☒		
2.4	Guardrail system: Top rail, mid-rail, and toe boards are secure and undamaged.	☒			FUNCTIONAL TEST				
2.5	Entrance gate / chain: Self-closing and self-latching (if so equipped).	☒			7.1	Ground Controls: All functions operate smoothly (lift, lower, extend, rotate).	☒		
2.6	Anchor points (for fall arrest): Present, undamaged, and clearly marked.	☒			7.2	Platform Controls: All functions operate smoothly from platform.	☒		
2.7	Fasteners, pins, and shafts: Secured, no visible wear or distortion.	☒			7.3	Emergency Stop: Functions from both ground and platform.	☒		
STABILIZATION & SUPPORT					7.4	Auxiliary/Manual Descent: Operates correctly and lowers platform.	☒		
3.1	Stabilizers/Outriggers: Deploy smoothly, no visible damage or leaks.	☒			7.5	Drive and steer functions: Operate correctly (test at low and high speed, if applicable).	☒		
3.2	Pad/Foot plates: Present, not worn out, and swivel freely.	☒			7.6	Tilt alarm/indicator: Functions correctly (simulate slope if safe).	☒		
3.3	Locking devices: All pins, latches, or locks function and secure properly.	☒			7.7	Load sensing system (if equipped): No fault codes visible.	☒		
3.4	Oscillating axle: Locking mechanism functions (if applicable).	☒			7.8	Horn and Alarms: Audible and functioning.	☒		
MECHANICAL & HYDRAULIC SYSTEMS					7.9	Pothole protection system (Scissor lifts): Deploys automatically when elevated.	☒		
4.1	Hydraulic hoses and fittings: No leaks, abrasion, kinks, or bubble/swelling.	☒			7.10	Platform overload indicator (if equipped): Functions correctly.	☒		
4.2	Hydraulic oil level: Correct (check sight glass/dipstick).	☒			SPECIFIC SAFETY DEVICES				
4.3	Cylinders: No visible damage, leaks, or rod scoring.	☒			8.1	Lanyard attachment points: Secure and undamaged.	☒		
4.4	Lubrication: All pivot points and moving parts are greased/lubricated.	☒			8.2	Motion alarms / beacon lights: Working (if applicable).	☒		
4.5	Cables and wire ropes: No fraying, broken strands, or corrosion; properly tensioned.	☒			8.3	Insulating boom (if applicable): Inspected per IEC/TS 61813.	☒		
4.6	Chains: Properly tensioned, lubricated, and no visible wear/stretch.	☒			8.4	Communication system (platform to ground): Working (if required).	☒		
ELECTRICAL SYSTEM									

Overall Comments

Inspected By : MOHAMED ABDUL BARICK	Customer Representative : ARIF
--	---------------------------------------



شركة ركن الهندسة للفحص والمعاينة المحدودة

ENGINEERING CORNER FOR INSPECTION CO. LTD.

Certificate Number: ECI/SA/C-01180/26





شركة ركن الهندسة للفحص والمعاينة المحدودة

ENGINEERING CORNER FOR INSPECTION CO. LTD.



ENGINEERING CORNER FOR
INSPECTION CO. LTD. (ECI)



ECI. 109092

Capacity : 500 LBS

Equipment No. : S26AJ-447

Serial No. : 0300239619

Inspected Date : 02-May-2026

Next Inspection : 01-Nov-2026

Inspector : MOHAMED ABDUL BARICK

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address:eci@eccgroupksa.com