



بروج للتأمين التعاوني  
Buruj Cooperative Insurance

### شهادة التأمين - CERTIFICATE OF INSURANCE

|                                      |   |                                 |   |                      |
|--------------------------------------|---|---------------------------------|---|----------------------|
| Policy Holder Name                   | : | Sudhir Equipment Rental Company | : | اسم حامل الوثيقة     |
| Policy Number                        | : | 01/CPM/ 2025/000002             | : | رقم الوثيقة          |
| Policy Period                        | : | 05/04/ 2025 to 04/04/2026       | : | فترة الوثيقة         |
| Description of Machinery / Equipment | : | DINGLI-AWPS-JCPT0807AC          | : | وصف المعدة/ال لة     |
| Chassis / Serial No.                 | : | JPAC024F03354                   | : | رقم الهيكل/ التسلسلي |
| Year of Manufacturing                | : | 2024                            | : | سنة الصنع            |
| Asset ID No.                         | : | SD8ESL-1474                     | : | رقم ال صل            |
| Location                             | : | Kingdom of Saudi Arabia.        | : | الموقع               |

BURUJ Cooperative Insurance Company certifies that above client is holding a Machinery/Equipment Insurance Policy for the above-mentioned Equipment in accordance with the above-mentioned Insurance Policy.

**With effect from:** 05/04/ 2025 to 04/04/2026

This Certificate has been issued upon Insured's request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تشهد شركة بروج للتأمين التعاوني بأن السادة أعل ه مؤمنين لديها تأمين المكانن/المعدات المذكورة أعل ه وذلك حسب وثيقة التأمين المذكورة أعل ه

والتي يبدأ تاريخ سريانها من ٢٠٢٥/٠٤/٠٥ إلى ٢٠٢٦/٠٤/٠٤

تم إصدار هذه الشهادة بناءً على طلب المؤمن له وذلك حسب الشروط وال استثناءات وال شتراطات المذكورة في الوثيقة.

#### Important Notices:

1. This Certificate does not pay any fines, penalties, bonds or cautions that may be imposed.
2. Original certificates are only accepted.
3. Due to the importance of correct information being stated in this certificate, kindly examine the document carefully and advise the Company of any difference.
4. In the event of changes in the above information, kindly contact +966-11-2938383

#### مل حظات هامة:

- ١) ل تطبق هذه الشهادة التأمين على الغرامات والعقوبات المالية بما في ذلك المخالفات أو الضمانات أو الكفالات التي قد تقرر.
- ٢) تقبل الشهادة ال صلية فقط.
- ٣) نظراً ل همية صحة البيانات الخاصة بكم في هذه الشهادة، الرجاء التأكد منها وإشعار الشركة في حالة وجود أي اختل فات.
- ٤) عند الحاجة إلى تعديل البيانات أعل ه يرجى ال اتصال على شركة بروج للتأمين التعاوني ٢٩٣٨٣٨٣-١١-٩٦٦+



**BURUJ Cooperative Insurance Company**

P.O. Box 51855, Riyadh 11553,  
National Address 3385, Al Thomamah Road, An-Nada District.  
800 124 0201 | burujinsurance.com

**Issue Date:** 3 April 2025

## OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

|                           |                         |
|---------------------------|-------------------------|
| <b>Equipment</b>          | <b>AWP</b>              |
| <b>Brand / Make</b>       | <b>DINGLI</b>           |
| <b>Asset ID</b>           | <b>SD8ESL-1474</b>      |
| <b>Model Number</b>       | <b>JCPT0807AC</b>       |
| <b>Serial Number</b>      | <b>JPAC024F03354</b>    |
| <b>Working Height</b>     | <b>08 Meter</b>         |
| <b>Type</b>               | <b>Electric Scissor</b> |
| <b>Manufacturing Year</b> | <b>2024</b>             |

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : [Info@sudhirrentals.com](mailto:Info@sudhirrentals.com)

Sincerely,

Ajay Koul  
General Manager  
Sudhir Equipment Rental Company





# شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

|                                           |                            |                                 |
|-------------------------------------------|----------------------------|---------------------------------|
| Date of thorough examination : 19-07-2025 | Date of issue : 19-07-2025 | Report No. : ESICO-LFT-R25-4941 |
|-------------------------------------------|----------------------------|---------------------------------|

| Name & Address of employer       |                                                                                                                                                                                     | Location             | Sticker No          | Standards         |
|----------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------|-------------------|
| SUDHIR EQUIPMENT RENTALS COMAPNY |                                                                                                                                                                                     | Riyadh               | 6593                | SASO GSO EN 280   |
| Equipment Identification No      | Equipment Description                                                                                                                                                               | Safe Working Load(s) | Date of Manufacture | Manufacturer Name |
| SD8ESL-1474 OR JPAC024F03354     | SCISSOR LIFT<br>MODEL: JCPT0807AC<br>Voltage: 24V Power: 3.0kW<br>Max. platform height:19 ftm<br>Max.number of occupatans: 2<br>Max.wind speed : 28 /mph<br>Machine weight:3586 lbs | RATED LOAD:<br>230K  | 2024                | DINGLI            |

|                                                                                         |                                              |                                                                   |                                              |
|-----------------------------------------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------|----------------------------------------------|
| Is this the first examination after installaton or assembly at a new site or location?  | Yes - No <input checked="" type="checkbox"/> | Was the examination carried out within an interval of? - 6 Months | Yes <input checked="" type="checkbox"/> No - |
| If the answer to the above question is YES, has the equipment been installed correctly? | Yes - No -                                   | In accordance with an examination scheme?                         | Yes <input checked="" type="checkbox"/> No - |
|                                                                                         |                                              | After the occurence of exceptional circumstances?                 | Yes - No <input checked="" type="checkbox"/> |

|                                                                                                                                                                        |              |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE             |              |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect?                                                                             | N/A          |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)                                                                | Yes by : N/A |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A                                                                  |              |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE                                                                            |              |
| Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory |              |



For confirmation scan QR code  
search with report number : ESICO-LFT-R25-4941

☒ Safe to operate

Next Inspection : 18-01-2026

Inspected by : Mohamed Askar Ali

