

## OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

|                           |                         |
|---------------------------|-------------------------|
| <b>Equipment</b>          | <b>Tower Light</b>      |
| <b>Brand / Make</b>       | <b>Sudhir</b>           |
| <b>Asset ID</b>           | <b>STL-469</b>          |
| <b>Model Number</b>       | <b>SGL-7.5</b>          |
| <b>Serial Number</b>      | <b>VEPL/2023-24/347</b> |
| <b>Rating</b>             | <b>1600 W</b>           |
| <b>Manufacturing Year</b> | <b>2023</b>             |

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : [Info@sudhirrentals.com](mailto:Info@sudhirrentals.com)

Sincerely,

Ajay Koul  
General Manager  
Sudhir Equipment Rental Company





بروج للتأمين التعاوني  
Buruj Cooperative Insurance

### شهادة التأمين - CERTIFICATE OF INSURANCE

|                                      |   |                                 |   |                      |
|--------------------------------------|---|---------------------------------|---|----------------------|
| Policy Holder Name                   | : | Sudhir Equipment Rental Company | : | اسم حامل الوثيقة     |
| Policy Number                        | : | 01/CPM/ 2025/000002             | : | رقم الوثيقة          |
| Policy Period                        | : | 05/04/ 2025 to 04/04/2026       | : | فترة الوثيقة         |
| Description of Machinery / Equipment | : | VARADA-Tower Light-SGL-7.5      | : | وصف المعدة/ال لة     |
| Chassis / Serial No.                 | : | VEPL/ 2023-24/ 347              | : | رقم الهيكل/ التسلسلي |
| Year of Manufacturing                | : | 2023                            | : | سنة الصنع            |
| Asset ID No.                         | : | STL-469                         | : | رقم ال صل            |
| Location                             | : | Kingdom of Saudi Arabia.        | : | الموقع               |

BURUJ Cooperative Insurance Company certifies that above client is holding a Machinery/Equipment Insurance Policy for the above-mentioned Equipment in accordance with the above-mentioned Insurance Policy.

**With effect from:** 05/04/ 2025 to 04/04/2026

This Certificate has been issued upon Insured's request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تشهد شركة بروج للتأمين التعاوني بأن السادة أعل ه مؤمنين لديها تأمين المكانن/المعدات المذكورة أعل ه وذلك حسب وثيقة التأمين المذكورة أعل ه

والتي يبدأ تاريخ سريانها من ٢٠٢٥/٠٤/٠٥ إلى ٢٠٢٦/٠٤/٠٤

تم إصدار هذه الشهادة بناءً على طلب المؤمن له وذلك حسب الشروط وال استثناءات وال شتراطات المذكورة في الوثيقة.

#### Important Notices:

1. This Certificate does not pay any fines, penalties, bonds or cautions that may be imposed.
2. Original certificates are only accepted.
3. Due to the importance of correct information being stated in this certificate, kindly examine the document carefully and advise the Company of any difference.
4. In the event of changes in the above information, kindly contact +966-11-2938383

#### مل حظات هامة:

- ١) ل تطبق هذه الشهادة التأمين على الغرامات والعقوبات المالية بما في ذلك المخالفات أو الضمانات أو الكفالات التي قد تفرض.
- ٢) تقبل الشهادة ال صلية فقط.
- ٣) نظراً ل همية صحة البيانات الخاصة بكم في هذه الشهادة، الرجاء التأكد منها وإشعار الشركة في حالة وجود أي اختل فات.
- ٤) عند الحاجة إلى تعديل البيانات أعل ه يرجى ال اتصال على شركة بروج للتأمين التعاوني ٢٩٣٨٣٨٣-١١-٩٦٦+



**BURUJ Cooperative Insurance Company**

P.O. Box 51855, Riyadh 11553,  
National Address 3385, Al Thomamah Road, An-Nada District.  
800 124 0201 | burujinsurance.com

**Issue Date:** 3 April 2025

CERTIFICATE NO  
INCRT33974

## CERTIFICATE OF THOROUGH EXAMINATION

21-SEP-2025

APPROVED

BY THIRD PARTY

TOWER LIGHT / STL-469

OWNER DETAILS  
SUDHIR EQUIPMENT RENTAL COMPANY  
AL AMIR MUHAMMED IBN FAHD ROAD Dammam  
Dammam  
Saudi Arabia

WORK ORDER : INSJO10322  
STICKER NO : 031018  
TAG NO : NA  
COLOR CODE : NA  
TIME SHEET NO : 27532  
CHECKLIST NO : ECKL24958

Quotation / RFI / RFI\_NO : NA//

ITEM DESCRIPTION : DIESEL POWERED TOWER LIGHT WITH POWER CAPACITY OF 4.5 kW

ITEM LOCATION : AL MADAYA

| VISUAL TEST                                                         | LOAD TEST                                                           | FUNCTIONAL TEST                                                     | WITNESS ONLY                                                        | TECHNICAL CONSULTANCY                                               |
|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|---------------------------------------------------------------------|
| <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

AT THE TIME OF INSPECTION BELOW DESIGNATED DETAILS ARE FOUND and THE ITEM WAS EXAMINED THROUGHOUT

|                                 |                                      |                         |                                   |
|---------------------------------|--------------------------------------|-------------------------|-----------------------------------|
| MANUFACTURER<br>VARADA ENERGIES | MODEL/TYPE<br>SGL7.5                 | MANUFACTURED ON<br>2023 | SERIAL NO<br>LT-239               |
| OWNER ID<br>STL-469             | ENGINE POWER<br>NA                   | ENGINE S/N<br>NA        | CAPACITY / S.W.L.<br>4.5 KW       |
| WORK PROCEDURE<br>NA            | STANDARD USED<br>BS EN 60034-22:2009 | PREVIOUS EXPIRY<br>NA   | PREVIOUS INSPECTION DETAILS<br>NA |

ATTACHMENT DETAILS : ☐ YES ☒ NO

| ITEM DESCRIPTION | MODEL/TYPE | SERIAL NO | CAPACITY | RESULT |
|------------------|------------|-----------|----------|--------|
| NA               | NA         | NA        | NA       | NA     |

RECOMMENDATION/CONCLUSION: FOUND SATISFACTORY

INSPECTION DATE : 20-SEP-2025

EXPIRY DATE : 19-MAR-2026

☒ APPROVED ☐ REJECTED

AUTHORIZED BY : Nahid Alam Siddquee

INSPECTED BY : Mohammad Faisal

*Nahid Alam Siddquee*



*M. Faisal*

## THROUGHOUT INSPECTION CHECKLIST AND REPORT

|                                                          |                          |                |
|----------------------------------------------------------|--------------------------|----------------|
| EQUIPMENT NAME                                           | WORK ORDER NO            | CHECKLIST NO   |
| TOWER LIGHT                                              | INSJO10322               | ECKL24958      |
| EQUIPMENTG DESCRIPTION                                   | DISCIPLINE               | OWNER ID       |
| DIESEL POWERED TOWER LIGHT WITH POWER CAPACITY OF 4.5 KW | PORTRAIT_CERTIFICATE_ONE | STL-469        |
| FACILITY/LOCATION                                        | STICKER NO               | COLOR CODE     |
| AL MADAYA                                                | 031018                   |                |
| PROJECT TITLE                                            | SERIAL NO                | CAPACITY (SWL) |
| NA                                                       | LT-239                   | 4.5 KW         |
| OWNER NAME                                               | MANUFACTURER             | MODEL/TYPE     |
| SUDHIR EQUIPMENT RENTAL COMPANY                          | VARADA ENERGIES          | SGL7.5         |

|             |                 |                 |
|-------------|-----------------|-----------------|
| WORK ORDER  | PO/QUOTATION NO | INSPECTION DATE |
| INCRT33974  | NA              | 20-Sep-2025     |
| EXPIRY DATE | RFI NO          | CERTIFICATE NO  |
| 19-Mar-2026 |                 | INCRT33974      |

| ITEM NO | ACCEPTANCE CRITERIA                                                                                                          | REFERENCE | PASS | FAIL | NA | REINS DATE |
|---------|------------------------------------------------------------------------------------------------------------------------------|-----------|------|------|----|------------|
| 1       | GENERAL REQUIRMENTS OF EQUIPMENT                                                                                             |           |      |      |    |            |
| 1.1     | Equipment document is available                                                                                              |           | PASS |      |    |            |
| 1.2     | Previous inspection reports are checked                                                                                      |           | PASS |      |    |            |
| 1.3     | Equipment is operated by a qualified operator                                                                                |           | PASS |      |    |            |
| 1.4     | Pre-use checklist maintained by the operator                                                                                 |           | PASS |      |    |            |
| 1.5     | Warning notices, caution, or restriction for safe operation are clearly displayed                                            |           | PASS |      |    |            |
| 1.6     | Mfg. name, serial no., model, and address are clearly marked or tagged                                                       |           | PASS |      |    |            |
| 1.7     | A sign is posted warning the operated not to rely solely on any automatic device as a substitute for safe operating practice |           | PASS |      |    |            |
| 1.8     | Working Environment is hazard free                                                                                           |           | PASS |      |    |            |
| 1.9     | SWL/No. of person clearly marked                                                                                             |           | PASS |      |    |            |
| 1.10    | Durable load chart is provided in as accessible location                                                                     |           | PASS |      |    |            |
| 2       | GENERAL CONDITIONS OF BASIC PARTS                                                                                            |           |      |      |    |            |
| 2.1     | Engine/Motor/Battery are in good and working condition                                                                       | 11.34     | PASS |      |    |            |
| 2.2     | Moving parts are guarded                                                                                                     |           | PASS |      |    |            |
| 2.3     | Access to the platform is provided by Ladders/Steps                                                                          |           | PASS |      |    |            |
| 2.4     | Steering system is working properly                                                                                          |           | PASS |      |    |            |
| 2.5     | Wind shield/Wipers/Mirrors are in good condition or working properly                                                         |           | PASS |      |    |            |
| 2.6     | Hand/Lever/Foot Brake System are in good condition                                                                           |           | PASS |      |    |            |
| 2.7     | Doors/Cabin/Cabin Access/Platform Access/Locks                                                                               |           | PASS |      |    |            |
| 2.8     | Seat Belt/Arm Rest                                                                                                           |           | PASS |      |    |            |
| 2.9     | Masts are correctly installed                                                                                                |           | PASS |      |    |            |
| 2.10    | Platform toe board (4")/ guardrails (3.5' ±3")                                                                               |           | PASS |      |    |            |
| 2.11    | There are no loose nuts, bolts, missing, worn, or damaged parts around the structure                                         |           | PASS |      |    |            |
| 2.12    | The equipment/Tool is free of defective and/or corroded joints/ members                                                      |           | PASS |      |    |            |
| 2.13    | Leak-free hydraulic/pneumatic/fuel/water                                                                                     |           | PASS |      |    |            |
| 2.14    | Equipment physical condition                                                                                                 |           | PASS |      |    |            |
| 2.15    | Equipment Operational condition                                                                                              |           | PASS |      |    |            |

No liabilities will be considered against UV Gulf Co. Ltd. for failure, damage or other occurrence to client owned or operated equipment due to misuse, improper installation, poor maintenance, environmental condition, nature disaster, operator mistakes and uncontrolled operation. The concerned Inspector or representative has thoroughly examined the item in accordance with relevant standards. Inspection indicates that the mentioned item/machine/tools has no apparent defects which may prove dangerous during normal operation and it's found satisfactory for further use under specified manufacturer manual/guide and operated by a certified operator. This certificate shall not be generated without an official approval in between UV Gulf and Client. This Certificate becomes invalid if any modification/alteration is made to the item.

| ITEM NO | ACCEPTANCE CRITERIA                                                                          | REFERENCE | PASS | FAIL | NA | REINS DATE |
|---------|----------------------------------------------------------------------------------------------|-----------|------|------|----|------------|
| 2. 16   | Clutches /Pedals/Hand lever system                                                           |           | PASS |      |    |            |
| 3       | GENERAL CONDITION OF ELECTRICAL SYSTEM                                                       |           |      |      |    |            |
| 3. 1    | Equipment internal computer or LMI is working properly                                       |           | PASS |      |    |            |
| 3. 2    | Identification/Warning indication is shown perfect                                           |           | PASS |      |    |            |
| 3. 3    | Travel alarm/reverse alarm/beacon alarm/tilt alarm/ platform lowering alarm                  |           | PASS |      |    |            |
| 3. 4    | Horn is working in good condition                                                            |           | PASS |      |    |            |
| 3. 5    | Power ratings are provided and marked (for AC and/or DC)                                     |           | PASS |      |    |            |
| 3. 6    | Electrical cables, fuses, wiring, and components are undamaged                               |           | PASS |      |    |            |
| 3. 7    | Lighting System/Cabin Light/Boom Light are installed and working                             |           | PASS |      |    |            |
| 3. 8    | Air conditioning system inside operator cabin is working                                     |           | PASS |      |    |            |
| 3. 9    | Pendant/Remote control all switches are working                                              |           | PASS |      |    |            |
| 3. 10   | Wires/Hoses are properly covered and arranged                                                |           | PASS |      |    |            |
| 4       | GENERAL CONDITION OF EQUIPMENT SAFETY FEATURES                                               |           |      |      |    |            |
| 4. 1    | Fire extinguisher (Inspected)                                                                |           | PASS |      |    |            |
| 4. 2    | Safety lock pins (lattice/hydraulic boom)                                                    |           | PASS |      |    |            |
| 4. 3    | Computer indicator (LMI/SLI)                                                                 |           | PASS |      |    |            |
| 4. 4    | An hour meter is fitted                                                                      |           | PASS |      |    |            |
| 4. 5    | Emergency stop button available at the platform control station                              |           | PASS |      |    |            |
| 4. 6    | Emergency stop button available at the ground control station                                |           | PASS |      |    |            |
| 4. 7    | Lowering/retracting is operable from the platform control                                    |           | PASS |      |    |            |
| 4. 8    | Lowering/retracting is operable from the ground control                                      |           | PASS |      |    |            |
| 4. 9    | Safety props or latches are installed                                                        |           | PASS |      |    |            |
| 4. 10   | A wind speed indicator is installed                                                          |           | PASS |      |    |            |
| 4. 11   | Anti-two-block system is installed                                                           |           | PASS |      |    |            |
| 4. 12   | Fuel/Hydraulic Gauges and indication                                                         |           | PASS |      |    |            |
| 4. 13   | Anti-collision system working                                                                |           | PASS |      |    |            |
| 4. 14   | Path track with front and rear camera                                                        |           | PASS |      |    |            |
| 4. 15   | An auxiliary power source is available (Ready to be used in the event of primary power loss) |           | PASS |      |    |            |
| 4. 16   | Maximum travel height and travel directions are clearly marked                               |           | PASS |      |    |            |
| 4. 17   | Maximum platform/boom height and reach the clear market                                      |           | PASS |      |    |            |
| 5       | GENERAL CONDITION OF MOVING PARTS                                                            |           |      |      |    |            |
| 5. 1    | All moving parts are lubricated                                                              |           | PASS |      |    |            |
| 5. 2    | Wheels/rollers/drums are working in good condition without any defect                        |           | PASS |      |    |            |
| 5. 3    | Wire rope/pully are installed and working in good condition                                  |           | PASS |      |    |            |
| 5. 4    | Swing control/swing breaking are in good condition and performing smooth                     |           | PASS |      |    |            |
| 5. 5    | Boom raise/extend (hydraulic/lattice) are in good condition                                  |           | PASS |      |    |            |
| 5. 6    | Fly jib/luffing jib are installed properly and working in good condition                     |           | PASS |      |    |            |
| 5. 7    | Outriggers are working without any leakage and all outriggers' pads are available            |           | PASS |      |    |            |
| 5. 8    | Upper/lower sheaves are working in good condition                                            |           | PASS |      |    |            |
| 5. 9    | Hooks (main hook/auxiliary hook) are working smooth with clear visible SWL mark              |           | PASS |      |    |            |
| 5. 10   | The hook is not bent or twisted Max. not to exceed 10°                                       |           | PASS |      |    |            |

| ITEM NO | ACCEPTANCE CRITERIA                                                                 | REFERENCE | PASS | FAIL | NA | REINS DATE |
|---------|-------------------------------------------------------------------------------------|-----------|------|------|----|------------|
| 5. 11   | The hook is not distorted in the throat opening max allowable throat opening is 15% |           | PASS |      |    |            |
| 5. 12   | Maximum wear in the hook bowl is not exceeding 10%                                  |           | PASS |      |    |            |
| 5. 13   | Operating/general levers operation is smooth without any leakage                    |           | PASS |      |    |            |
| 5. 14   | Attachments fork/bucket/jackhammer is working in good condition                     |           | PASS |      |    |            |
| 5. 15   | Lift and lower operation are smooth without any slippage                            |           | PASS |      |    |            |
| 5. 16   | Trolley/girder are running properly                                                 |           | PASS |      |    |            |
| 5. 17   | Rail (certified alignment paper) are checked and maintained by operator             |           | PASS |      |    |            |
| 5. 18   | Upper and lower limit are working in good condition                                 |           | PASS |      |    |            |
| 5. 19   | Bridge/trolley drive wheel are working in good condition                            |           | PASS |      |    |            |
| 5. 20   | Travel brakes and locks for wheel mounted crane/ crawler crane                      |           | PASS |      |    |            |
| 5. 21   | Pendant trolley festoon is in good condition                                        |           | PASS |      |    |            |
| 5. 22   | Drive chains are correctly tensioned                                                |           | PASS |      |    |            |
| 5. 23   | Values of inspection                                                                |           | PASS |      |    |            |

This checklist is an official document approved by UV Gulf. Signing this document will prove that the work has been accomplished and the client has taken services from UV Gulf under official approvals from both sides. Cancellation of checklist must goes under UV Gulf management approvals before signing. Any alteration or modification on checklist has been made without designated personnel signature and stamp or official approval from UV Gulf will be consider rejected.

|                                                       |                                    |
|-------------------------------------------------------|------------------------------------|
| INSPECTED BY<br>MOHAMMAD FAISAL                       | APPROVED BY<br>NAHID ALAM SIDDQUEE |
| CLIENT REPRESENTATIVE/SUPERVISOR DETAILS<br>MR SHAMIR | CLIENT REPRESENTATIVE ID NO<br>NA  |







## شركة خليج التعقيب الموحد للفحص

7158 King Khalid St, Al Khobar, Saudi Arabia 34427

Telephone : +966 1383 11390 Fax : +966 1383 12077

Email : info@uvgulf.com Website : www.uvgulf.com

APPROVED

STICKER NO 031018

|                     |                              |
|---------------------|------------------------------|
| EQUIPMENT NAME / ID | TOWER LIGHT / STL-469        |
| INSPECTION TYPE     | Visual Test, Functional Test |
| SERIAL NO           | LT-239                       |
| S.W.L               | 4.5 KW                       |
| INSPECTION DATE     | 20-SEP-2025                  |
| EXPIRY DATE         | 19-MAR-2026                  |



| BOOM LENGTH | % S.W.L |           | LOAD CHART |  |
|-------------|---------|-----------|------------|--|
|             | RADIUS  | TEST LOAD | S.W.L      |  |
|             |         |           |            |  |
|             |         |           |            |  |
|             |         |           |            |  |

INSPECTED BY: Mohammad Faisal

CERTIFIED VENDOR'S OF

SAUDI ARAMCO 10108615 | SEC 0005022158 | SWCC 0001003426 | SAR 3573 | KAFA 784

SEE INSPECTION REPORT FOR DETAILS:

This sticker is issued by UV Gulf and any type of edit, overwrite, replace and erase by unauthorized person is liable to rejection of this sticker

