


Ownership Certificate

To Whom It May Concern

This is to certify that the following equipment mentioned below are the sole owned by Sudhir Equipment Rental Company

Equipment	Tower Light
Brand / Make	VARADA
Asset ID	STL-535
Model Number	SGL-7.5
Serial Number	VEPL/2023-24/408
Engine Serial Number	5329300486
Rating	1600 W
Year of Manufacturing	2023



Authorized Signature

Sudhir Equipment Rental Company
Kingdom of Saudi Arabia





بروج للتأمين التعاوني
Buruj Cooperative Insurance

شهادة التأمين - CERTIFICATE OF INSURANCE

Policy Holder Name	:	Sudhir Equipment Rental Company	:	اسم حامل الوثيقة
Policy Number	:	01/CPM/ 2025/000002	:	رقم الوثيقة
Policy Period	:	05/04/ 2025 to 04/04/2026	:	فترة الوثيقة
Description of Machinery / Equipment	:	VARADA-Tower Light-SGL-7.5	:	وصف المعدة/ال لة
Chassis / Serial No.	:	VEPL/ 2023-24/ 408	:	رقم الهيكل/ التسلسلي
Year of Manufacturing	:	2023	:	سنة الصنع
Asset ID No.	:	STL-535	:	رقم ال صل
Location	:	Kingdom of Saudi Arabia.	:	الموقع

BURUJ Cooperative Insurance Company certifies that above client is holding a Machinery/Equipment Insurance Policy for the above-mentioned Equipment in accordance with the above-mentioned Insurance Policy.

With effect from: 05/04/ 2025 to 04/04/2026

This Certificate has been issued upon Insured's request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تشهد شركة بروج للتأمين التعاوني بأن السادة أعل ه مؤمنين لديها تأمين المكانن/المعدات المذكورة أعل ه وذلك حسب وثيقة التأمين المذكورة أعل ه

والتي يبدأ تاريخ سريانها من ٢٠٢٥/٠٤/٠٥ إلى ٢٠٢٦/٠٤/٠٤

تم إصدار هذه الشهادة بناءً على طلب المؤمن له وذلك حسب الشروط وال استثناءات وال شتراطات المذكورة في الوثيقة.

Important Notices:

1. This Certificate does not pay any fines, penalties, bonds or cautions that may be imposed.
2. Original certificates are only accepted.
3. Due to the importance of correct information being stated in this certificate, kindly examine the document carefully and advise the Company of any difference.
4. In the event of changes in the above information, kindly contact +966-11-2938383

مل حظات هامة:

- ١) ل تطبق هذه الشهادة التأمين على الغرامات والعقوبات المالية بما في ذلك المخالفات أو الضمانات أو الكفالات التي قد تقرر.
- ٢) تقبل الشهادة ال صلية فقط.
- ٣) نظراً ل همية صحة البيانات الخاصة بكم في هذه الشهادة، الرجاء التأكد منها وإشعار الشركة في حالة وجود أي اختل فات.
- ٤) عند الحاجة إلى تعديل البيانات أعل ه يرجى ال اتصال على شركة بروج للتأمين التعاوني ٢٩٣٨٣٨٣-١١-٩٦٦+



BURUJ Cooperative Insurance Company

P.O. Box 51855, Riyadh 11553,
National Address 3385, Al Thomamah Road, An-Nada District.
800 124 0201 | burujinsurance.com

Issue Date: 3 April 2025



REPORT OF INSPECTION

Cert. No.: 2128024	Date of Examination: 05/01/2026	Sticker No.: 01-90012
Equipment Owner	Sudhir Equipment Rental Company	
Place of Inspection	Dammam Yard.	
Equipment Type	Portable Tower Light.	
Manufacturer Name	VARADA	
Owner ID	STL-535	
Serial No.	VEPL/2023-24/408	
Model	SGL-7.5	
No. of Lamp(s) & Power	4 LAMPS / 7.5 KVA	
Vertical Mast Height (max)	8.5 Mtr	
Nature of Power	Diesel	

At the request of Sudhir Equipment Rental Company, Surveyor to BUREAU VERITAS, acting within the General Conditions of Services of the Society, attended on 05/01/2026 at Dammam Yard. to witness Test and/or to carry out Thorough Examination of the above-mentioned equipment as per EN 60204, ISO 8528

Inspection Activities:

Prior to commencing performance test, visual inspection of the equipment was carried out and no visible defects were observed. The equipment was then operated to all the functions to verify the performance of the equipment.

Result of Inspection:

Based on the visual inspection of the Portable Tower Light. and upon post-performance test & thorough examination, the above mentioned equipment has been found free from damage and/or permanent deformation at the time of inspection & is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

Remarks:

- Maintain regular maintenance.
- Maintain regular housekeeping.

Next Inspection Due on or before: 04/07/2026

Issued at Al Khobar on 05/01/2026

Inspected by

Signature:



Name: Mohamed Elsbary
Position: Inspector



Reviewed by
Signature:



Name: Ahmed Elabady
Position: Reviewer

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.


This not is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



CHECKLIST OF TEST AND THOROUGH EXAMINATION

Inspection Sticker No.: 01-90012		Date of Examination: 05/01/2026
DESCRIPTION		CONDITION/REMARKS
1.	Condition of the mast	Satisfactory
2.	Condition of mast winch	Satisfactory
3.	Condition of mast cable	Satisfactory
4.	Condition of mast cradle locking pin	Satisfactory
5.	Condition of light fixtures	Satisfactory
6.	Condition of electrical box & wiring	Satisfactory
7.	Condition of light lens	Satisfactory
8.	Condition of energy source	Satisfactory
9.	Fire extinguisher (if fitted)	Satisfactory
10.	Ignition & electrical system condition	Satisfactory
11.	Exhaust & ventilation	Satisfactory
12.	Power generator set (if applicable)	Satisfactory
13.	Marking / Labels & warning signage	Satisfactory
14.	Foundation – tires, out-riggers, support stands	Satisfactory
15.	Structure – chassis, lifting points	Satisfactory
16.	Name plate	Satisfactory
Remarks: -		

Inspector to Bureau Veritas
Signature:




Name: Mohamed Elsabry
Position: Inspector

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This not is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



AR HOUSE EXPORTER
TALEGAON MIDC. BADHALWADI.
DIST - PUNE - 410507
mail : sales@varadaenergies.com

INDIA

VARADA ENERGIES PVT. LTD.

VEPL/ 2023-24/408

DEC-23

7.5 KVA DG SET WITH
LIGHTING TOWER 8.5 METERS

SGL-7.5

2800KG

No. LFT-S.

01 - 90012



BUREAU
VERITAS

Saudi Arabia

Tel: +966 13 882 1071

Fax: +966 13 882 1072



EQUIP. NO. STL - 535

EQUIP. S N. VEPL/2023-24/408

S. W. L: N/A

DATE OF INSPECTION 05-Jan-2026

NEXT INSPECTION DUE ON 04-Jul-2026

INSPECTED BY Mohamed Limby

This sticker is issued under Bureau veritas General
Conditions of Service and is valid only in conjunction
with hereafter inspection Report No.
Report No. LFT-R