THOROUGH EXAMINATION CERTIFICATE OF GENERATOR

Report No:	TUR-INS-2026-09-04999	**Report Issue Date:**	03-Sep-2026
Customer Name:	Sudhir Equipment Rental Company	**Inspection Type:**	Functional & Visual Check
Address:	Dammam,Ksa	**Serial Number**	GIM125.M3.T25.1357
Site Location:	Al-Turaif,Ksa	**Equipment Id Number:**	SG-1469-125
Standard Reference:	ISO 8528-5:2022	**Manufacturer:**	Mahindra
Inspection Date:	02-Sep-2026	**Equipment Model/Type:**	DG-125M3.SEB202
Next Inspection Date:	01-Sep-2027	**Sticker No:**	TUR/003970

Description		Capacity/SWL	Reason For Examination	Result	Safe To Use
Rated Power	100 KW	Rated Prime Power : 125 KVA	C	Satisfactory	YES
Rated Voltage	100 Volt				
Rated Current	180 Amps				
Weight	1856 Kg				
Rated Power Factor	0.8Φ				
Fluid Levels & Systems	Satisfactory				
Electrical & Battery	Satisfactory				
Control Panel & Grounding	Satisfactory				
Mechanical & Physical Condition	Satisfactory				
Emergency stop button	Satisfactory				
Fire extinguisher	Satisfactory				
Internal Visual Test	Satisfactory				
General Surface Test	Satisfactory				

Reason For Exam.	A 3 Months	B 6 Months	C 12 Months	D Written Scheme	E Exceptional Circumstance	F Installation

Result	ACCEPTED	REJECTED (See Attached Defect Report)

Declaration:

I hereby declare that the above information is correct and that the equipment has been thoroughly examined as far as possible in accordance with the appropriate provisions/Standards that at the time of the Inspection/examination and found to be free from any defect likely to affect safety other than theses detailed above.

Inspected By:	UIC 59 INSPECTOR	**Approved By:** MOHAMED NOORUL AMEEN	**Signature:** QA/QC
Stamp By:		**Designation:** Inspection Supervisor	

No liability will be considered against **UNIVERSAL INSPECTION COMPANY** for failure, damage or other occurrence to Client owned or operated equipment due to misuse, improper installations, poor maintenance, weather/environmental conditions & equipment operator/user mistakes or uncontrolled operation & maintenance.
This Inspection Certificate/Report shall not be reproduced except in full without the approval UIC and the Client.

VENDOR ID: 1004457 | APPROVED VENDOR | VENDOR ID : 11052442 | VENDOR ID: 5014041 | VENDOR ID: 10857