مؤسسة جبال هيما لايا للفحص

JABAL HEMALAYA FOR INSPECTIONS

Certificate of Thorough Visual and Functional Examination of Telehandler

Certificate No: JHI-6822-26-C2 | **Date of Inspection: 05-03-2026**

Name of the owner company: SUDHIR EQUIPMENT RENTAL COMPANY	**Location:** JEDDAH- KSA
Equipment Details:	TELESCOPIC HANDLER
Reference Regulations:	**Maker & Date of Manufacture:**
SASO-ISO-11525-2 ,BS EN 1459-1:2017+A1:2020	JLG & 2019

Traffic Plate No:	Owner No.	Model No.	Chassis No. / Serial No.
N/A	STH14017-003	4017RS	E160000290
Sticker No.	**Lift Capacity at full Height.**	**Max. Height of Lift**	**Dimension (LxWxH).**
014309	2500Kg	17.0 m	N/A

Maximum Lifting Capacity	4000Kg

Description of Test:
Note: Visual and Functional Test Were Satisfactory.

Date of Last Examination	Date of Next Examination
N/A	04-09-2026

RECOMMENDATION / REMARKS
At the time of Inspection, the Equipment was found Satisfactory.

IMAGES FOR TELESCOPIC



*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.
THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: **M.SHEIK ALLAVUDEEN** Surveyor's Name: **KHAIF**

Authorized Signature: Surveyor's Signature:

مؤسسة جبال هيما لايا للفحص
1010927177 :س.ت
Est. JABAL HEMALAYA For Inspections

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.
Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Annex to Certificate of Test and Thorough Examination

Certificate No.: JHI-6882-26-C2 **Date of Inspection:** 05-03-2026

S/No	Description	Condition / Remarks
1	Equipment Documents	Satisfactory
2	Control lever marking	Satisfactory
3	Attachment Fixing Pins / Locks	Satisfactory
4	Hydraulic Cylinders / Hydraulic System	Satisfactory
5	Telescopic Cylinders	Satisfactory
6	Stabilizer	Satisfactory
7	Boom Structure	Satisfactory
8	Gauges in Cab	Satisfactory
9	Wind Shield	Satisfactory
10	Seat belt / Seat Bar	Satisfactory
11	Motion Warning Alarm / Horn	Satisfactory
12	Rotating Warning Light / Reverse Alarm	Satisfactory
13	Operation Controls	Satisfactory
14	Electrical Cabling and Fittings	Satisfactory
15	Battery Condition / Connections	Satisfactory
16	Brakes	Satisfactory
17	Lights	Satisfactory
18	Fire Extinguisher	Satisfactory
19	Housekeeping	Satisfactory
20	Manufacturer's manuals	Satisfactory
21	Capacity Labels	Satisfactory
22	Machine Guard	Satisfactory
23	Engine / Engine Compartment	Satisfactory
24	Spark Arrestor	Shall be fitted when operating in highly explosive areas
25	Painting/Corrosion / General Status - Visual	Satisfactory
26	Maintenance Status record	Satisfactory
27	Record of Major Alterations or Repair	Satisfactory

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: KHAIF **Surveyor's Signature:**

