ESICO

شركة مساندة الإعمار للفحص
Emaar Support Inspection Co.
6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817
Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444
Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 08-09-2026	Date of issue : 08-09-2026	Report No. : ESICO-LFT-R26-10993

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY	DAMMAM	12645	SASO GSO EN 280

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
Z62D-347 OR S20AG-497	MANLIFT MODEL: Z62/40 TYPE: ARTICULATED BOOM MAX HEIGHT: 20 MTRS MAX HORIZONTAL REACH: 12.42 MTRS	230 KG	2018	GENIE

Is this the first examination after installaton or assembly at a new site or location?	Yes	-	No	✗	Was the examination carried out within an interval of?	-	6 Months
If the answer to the above question is YES, has the equipment been installed correctly?	Yes	-	No	-	In accordance with an examination scheme?	Yes ✓	No -
					After the occurence of exceptional circumstances?	Yes -	No ✗

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : NO DEFECT FOUND AT THE TIME OF INSPECTION	

For confirmation scan QR code
search with report number : ESICO-LFT-R26-10993

QA/QC DEPARTMENT
EMAAR SUPPORT INSPECTION CO.

✓ Safe to operate

Next Inspection : 07-03-2027

Inspected by : ANSON

INSPECTOR
C.R.: 2054100036

LEEA Full Member
أرامكو السعودية saudi aramco 10056897
EP-Q4634
NEOM نيوم 1100004098
شركة المياه الوطنية National Water Company 33564
10739
سابك sabic 001052261
الشركة السعودية للكهرباء Saudi Electricity Company 05022531
IAF
IAS ACCREDITED

Checklist - Mobile Elevated Work Platform Inspection

Item Name	Sat	Unsat	NA
UNIT INSPECTION ITEM AND DESCRIPTION			
The manufacturer's operations manual is stored on the unit	✓	-	-
Operating and emergency controls are in proper working condition (including emergency stop mechanism)	✓	-	-
Functional platform drive controls are in proper working condition	✓	-	-
The emergency lowering mechanism operates properly	✓	-	-
Lower operating controls successfully override the upper controls	✓	-	-
Both upper and lower controls are adequately protected from inadvertent operation	✓	-	-
The control panel is clean, and all buttons/switches are clearly visible	✓	-	-
All switches and mechanical guards are in good condition and properly installed	✓	-	-
All safety indicator lights work	✓	-	-
All drive controls function properly and are accurately labelled	✓	-	-
Motion alarms function properly	✓	-	-
Safety decals are in place and readable	✓	-	-
All guard rails are sound and in place, including basket chains	✓	-	-
Work platform and extension slides are clean, dry, and clear of debris	✓	-	-
Models with platform extensions: slides in and out freely with functioning safety locking pins	✓	-	-
Inspect for defects, including cracked welds, fuel leaks, hydraulic leaks, damaged control cables or wire harness, etc.	✓	-	-
Tires and wheels are in good condition with adequate air pressure if pneumatic	✓	-	-
Braking devices are operating properly	✓	-	-
Oil level/Hydraulic Oil Level/Fuel Level/Coolant Level is acceptable	✓	-	-
Battery Charge is acceptable	✓	-	-
Outriggers in place or functioning, and associated alarms working	✓	-	-

For confirmation scan QR code
search with report number : **ESICO-LFT-R26-10993**

QA/QC DEPARTMENT
EMAAR SUPPORT INSPECTION CO.

✓ Safe to operate

Next Inspection : 07-03-2027

Inspected by : ANSON

EMAAR SUPPORT INSPECTION CO.
INSPECTOR
C.R.: 2054100036

LEEA Full Member
أرامكو السعودية saudi aramco 10056897
EP-Q4634
NEOM نيوم 1100004098
شركة المياه الوطنية National Water Company 33564
10739
سابك sabic 001052261
الشركة السعودية للكهرباء Saudi Electricity Company 05022531
IAF INTERNATIONAL ACCREDITATION FORUM
IAS ACCREDITED