

CERTIFICATE OF THOUGH EXAMINATION OF FLOOD TOWER LIGHT

Date of thorough examination : 04-08-2026		Date of issue : 04-08-2026		Report No. : ESICO-LFT-R26-10251	
Name & Address of employer		Location		Sticker	
SUDHIR EQUIPMENT RENTALS		P3 SEVEN DAMMAM		11903	
Standards					
SASO- ISO -8528-6					
Equipment Identification No		Equipment Description		Safe Working Load(s)	
STL-648 OR VEPL/2024-25/137		TOWER LIGHT MODEL: SGL-7.5 RATED POWER: 1600W		1600W	
				Date of Manufacture	
				2024	
				Manufacturer Name	
				UNKNOWN	
Is this the first examination after installaton or assembly at a new site or location?			Yes ☐ - No ☒		
If the answer to the above question is YES, has the equipment been installed correctly?			Yes ☐ - No ☐		
Was the examination carried out within an interval of?			- 6 Months		
In accordance with an examination scheme?			Yes ☒ No ☐		
After the occurence of exceptional circumstances?			Yes ☐ - No ☒		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE					
Particulars of any tests carried out as part of the examination (if none state NONE) : FUNCTIONAL TEST					
Observation/additional comments relative to this thorough examination : IN GOOD CONDITION					



For confirmation scan QR code
search with report number : **ESICO-LFT-R26-10251**



☒ Safe to operate

Next Inspection : 03-02-2027

Inspected by : HENDRICKS

