



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF GENERATOR SET

Date of thorough examination : 05-07-2026	Date of issue : 05-07-2026	Report No. : ESICO-LFT-R26-9798		
Name & Address of employer	Location	Sticker	Standards	
SUDHIR EQUIPMENT RENTALS	2ND INDUSTRIAL CITY DAMMAM	11450	SASO ISO12100	
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SG-992-500 OR VEPL/2024-25/42	DIESEL GENERATOR MODEL: VEPL-500-CDP PRIME POWER: 455 KVA STANDBY POWER: 500 KVA ENGINE MODEL: 6BTAA5. 9-G6 FREQUENCY: 50 HZ /60 HZ POWER FACTOR: 0.8 LAGGING	VOLTAGE: 230 / 400 V	2024	VARADA
Is this the first examination after installaton or assembly at a new site or location?		Was the examination carried out within an interval of? - 6 Months		
Yes - No ☒		Yes ☒ No -		
If the answer to the above question is YES, has the equipment been installed correctly?		After the occurence of exceptional circumstances?		
Yes - No -		Yes - No ☒		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE				
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?				No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)		Yes by : N/A		
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE				
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST				
Observation/additional comments relative to this thorough examination : AT THE TIME OF INSPECTION THE NAME ABOVE EQUIPMENT WAS SAFE FOR OPERATION.				



For confirmation scan QR code
search with report number : ESICO-LFT-R26-9798

☒ Safe to operate

Next Inspection : 04-01-2027

Inspected by : Eric Kwesi Ankomanyi





أرامكو السعودية
saudi aramco
10056897



Print