



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION OF AIR COMPRESSOR

Date of thorough examination : 21-01-2026	Date of issue : 21-01-2026	Report No. : ESICO-LFT-R25-6338
---	----------------------------	---------------------------------

Name & Address of employer	Location	Sticker	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY	RIYADH YARD	7990	BS EN 1012-1

Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SAC-825-304 OR PE2461115	AIR COMPRESSOR MODEL:XAS 825-125 SKID POWER:209KW SPEED:1900RPM WORKING PRESSURE:8.6BAR/125PSI FREE AIR DELIVERY:10-24M ³ /MIN	WEIGHT BOX UNIT:APPROXIMATELY 1600KG	2024	ATLAS COPCO (INDIA) LTD.

Is this the first examination after installaton or assembly at a new site or location?	Yes - No ☒	Was the examination carried out within an interval of? - 6 Months	Yes ☒ No -
If the answer to the above question is YES, has the equipment been installed correctly?	Yes - No -	In accordance with an examination scheme?	Yes ☒ No -
		After the occurence of exceptional circumstances?	Yes - No ☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	No
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : NONE	
Particulars of any tests carried out as part of the examination (if none state NONE) : VISUAL INSPECTION AND FUNCTIONAL TEST.	
Observation/additional comments relative to this thorough examination : AT THE TIME OF INSPECTION MENTION ABOVE NAME OF EQUIPMENT WAS SATISFACTORY.	



☒ Safe to operate

Next Inspection : 20-07-2026

Inspected by : Jay Prakash



For confirmation scan QR code
search with report number : ESICO-LFT-R25-6338

