




Client Name & Address:	Sudhir Rental		
Work Order No.	ZAM-5009-02-24	Report No.	ZAMIL-R14474 / VIS
Place Of Inspection	Sudhir Rental Yard Sudhir Rental Yard	Report Date	10/02/2024
Date of Last Inspection	N/A	Date of Inspection	08/02/2024
Customer Requisition No.	N/A	Date of Next Inspection	07/08/2024
Applicable Standards	ISO 8528-3-2020	Issued Sticker No.	ZAM-W-16980
O.E.M / C.O.C No. / Drawings	Available	Color Code (If Applicable)	NA
Equipment Used	N/A	Model No.	N/A

Equipment Serial No.	Equipment I.D	QTY	Description	Capacity/SWL (Ton)
VEPL/2018-19/0034	SG-363-500	01	Generator Engine SN : MGBF5083N09716D Alternator No : N19A051681 Eng. Model : 2506A-E15TAG2 Eng.Maker : PERKINS Note : Visual inspection and functional test has been performed on the above mentioned equipment, during the time of inspection no any abnormality found.	N/A

Is this the first examination after installation or assembly at a new site or location:	☐ YES ☒ NO
If the answer to the above question is YES. Has the equipment been installed correctly?	☐ YES ☐ NO ☒ NA
Was the thorough examination carried out Within an interval of 3 months?	☐ YES ☒ NO
Was the thorough examination carried out Within an interval of 6 months?	☒ YES ☐ NO
Was the thorough examination carried out Within an interval of 12 months?	☐ YES ☒ NO
In accordance with an examination scheme?	☒ YES ☐ NO
After the occurrence of exceptional circumstances?	☐ Yes ☒ No
Identification of any part found to have a defect which is or could become a danger to person and a description of the defect (if none state none): NONE	
Is the above a defect which is of immediate danger to persons	☐ YES ☒ NO
Is the above a defect which is not yet but could become a danger to persons? (If yes state the day by when)	☐ YES ☒ NO Date:
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE): NONE	
Inspection Result:	During the time of Inspection Result found satisfactory - Is this Equipment Safe to Operate? ☒ YES ☐ NO
This certificate by company under its general conditions of services. This issuance of this certificate does not exonerate the buyers or sellers from exercising all their rights discharging all their liabilities under the contacts of sale. Stipulations to contrary are not binding on the company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the free or commission. The above findings are limited to date place of intervention only. The company is neither an insurer not a guarantor disclaims all liabilities in such capabilities.	

Inspected By Qualified: LEEA & ASNT NDT Level II		Reviewed By		Stamp
Name:	Mohamed Saad Kamel Diab	Name:	Mohamed Atwa	
Position:	Inspector	Position:	Technical supervisor	
Signature:		Signature:		



Name and address of employer of persons making and authenticating this report: Zamil Inspection & Contracting Co, King Fahad Road-Al-Dhabab Avenue-Dammam 32261
C.R.: 2050069798-Email: operations@zamil.sa



Zamil Inspection & Contracting Co.



+966555052687



info@zamil.sa



NO. ZAM-W-16980

Equipment Type : Generator
capacity/SWL : N/A
Equipment ID : SG-363-500
Equipment S.N. : VEPL/2018-19/0034
Inspection Date : 08/02/2024
Next Insp Date : 07/08/2024
Inspected By : Mohamed Saad Kamel Diab



Corporate Partner