


☐ Interim
☒ Final

INSPECTION REPORT

NO. R114200601.05

BV Job nr: KHO.INI.19.079SA

PROJECT: Third Party Inspection for Generator	Ref: KHO.INI.19.079SA
BV Client: Branch Of Sudhir Gensets Limited	P/o nr: N/A (client to BV)
Manufacturer: Ashok Leyland	

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST Generator	SN:VEPL/2018-19/0032 TAG ID:SG-411-125	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No				
Title	Reference n°	Rev.	Approved by	Date
EQUIPMENT DATA SHEET	-	-	-	-

INSPECTIONS : <u>Inspection place & Date or Period:</u> GzGCP-01 (Ghazal Gas Compression Project), June, 01, 2020 <u>Stage of inspection :</u> ☐ Before manufacturing ☐ During manufacturing ☒ Final ☐ Packing <u>Type of inspection:</u> ☐ Pre-inspection meeting ☐ Document and QC record review ☒ Visual examination, checks ☐ Witnessing tests ☐ Manufacturing progress status ☐ Vendor assessment ☒ Final inspection ☐ Packing (for details see continuation sheet) <u>Stamping:</u> ☒ No ☐ ☐	<u>Results of inspection :</u> ☒ Satisfactory ☐ Unsatisfactory <u>Non Conformities Reports (NCR):</u> o NCR's issued during reported period : N/A o List of outstanding NCR's : N/A <u>Main Conclusions & Remarks:</u> (for details see continuation sheet) Third party visual inspection and functional test of one unit of Generator was carried out and found satisfactory at the time of Inspection. Valid Sticker Number : LFT-S-01-21215 Next visit scheduled: May 31, 2021
--	--

☐ Interim
☒ Final

INSPECTION REPORT

NO. R114200601.05

BV Job nr: KHO.INI.19.079SA

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of **Branch Of Sudhir Gensets Limited** on the purpose of Third Party Inspection of One **Generator**

with Model No.:VEPL-125-CDP with Serial Number: VEPL/2018-19/0032.

2. Attendees : Branch Of Sudhir Gensets Limited

3. Scope of Inspection :

a. Visual Inspection & Functional Test of **Generator**

1- General Data

Equipment Type	Generator
Manufacturer	Ashok Leyland
Model	VEPL-125-CDP
Serial No.	VEPL/2018-19/0032



☐ Interim
☒ Final

INSPECTION REPORT

NO. R114200601.05

BV Job nr: KHO.INI.19.079SA

3- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Check engine oil level (check for proper oil level)	Pass	Found good condition.
4. Check for Descending output (Rated power (kw), Rated current(DCA), Rated voltage(DCV), Idle voltage(DCV), Rated duty cycle(%))	Pass	Found good condition.
5. Checked for Engine filter and oil Level	Pass	Found good condition.
6. Check for Accessorial Receptacle	Pass	Found good condition.

➤ **Conclusion:**

The **Generator** found in good running condition at the time of Inspection.

Inspected by:



ALI ALHOMOUD
IVS- Equipment Inspector



Checked by:



IVS- Inspection Team Leader

Date of issue: 03 June 2020

Inspection centre: BUREAU VERITAS ALKHOBAR