



# INSPECTION REPORT

## NO. R109210121.1

Interim  
Final

BV Job nr: KHO.INI.21.09.SA

|                                               |                               |
|-----------------------------------------------|-------------------------------|
| PROJECT: Third Party Inspection for GENERATOR | Ref: KHO.INI.18.002.SA.       |
| BV Client: SUDHIR                             | P/o nr: N/A<br>(client to BV) |
| Manufacturer: VARADA ENERGIES PVT             |                               |

| SUPPLY / SUBJECT OF INSPECTION                      | SN / TAG Nr                     | QTY |
|-----------------------------------------------------|---------------------------------|-----|
| VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERATOR | SG-481-125<br>VEPL/2020-21/0035 | 1   |

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: Yes No

| Title                | Reference n° | Rev. | Approved by | Date |
|----------------------|--------------|------|-------------|------|
| EQUIPMENT DATA SHEET | -            | -    | -           | -    |

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>INSPECTIONS :</b><br><u>Inspection place &amp; Date or Period:</u><br><b>Sudhir yard / JAN 21, 2021</b><br><u>Stage of inspection :</u><br>Before manufacturing<br>During manufacturing<br>Final<br>Packing<br><br><u>Type of inspection:</u><br>Pre-inspection meeting<br>Document and QC record review<br>Visual examination, checks<br>Witnessing tests<br>Manufacturing progress status<br>Vendor assessment<br>Final inspection<br>Packing<br>(for details see continuation sheet)<br><br><u>Stamping :</u><br><div style="display: flex; justify-content: space-around; align-items: center;"> <span>No</span> </div> | <b>Results of inspection :</b> Satisfactory    Unsatisfactory<br><br><u>Non Conformities Reports (NCR):</u><br><input type="checkbox"/> NCR's issued during reported period : N/A<br><input type="checkbox"/> List of outstanding NCR's : N/A<br><br><u>Main Conclusions &amp; Remarks:</u> (for details see continuation sheet)<br><br>Third party visual inspection and functional test of one unit of <b>GENERATOR</b> was carried out and found satisfactory at the time of Inspection.<br><br><b>Valid Sticker Number :</b> 20-25504<br><b>Next visit scheduled:</b> JAN 20, 2022 |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|



BUREAU  
VERITAS**INSPECTION REPORT****NO. R109210121.1**Interim  
Final

BV Job nr: KHO-IVS-21.09.SA

**Description of the inspections carried out:****1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of **SUDHIR** on the purpose of Third Party Inspection of One **GENERATOR** with Serial Number: VEPL/2020-21/0035

**2. Attendees :**

- Mahtab

**3. Scope of Inspection :**a. Visual Inspection & Functional Test of **GENERATOR****1- General Data**

|                |                     |
|----------------|---------------------|
| Equipment Type | GENERATOR           |
| Manufacturer   | VARADA ENERGIES PVT |
| Rating KW      | 100 KW              |
| Serial No.     | VEPL/2020-21/0035   |



BUREAU  
VERITAS

## INSPECTION REPORT

NO. R109210121.01

Interim  
Final

BV Job nr: KHO-IVS-2017-23

## 3- Inspection and Test Results

| Acceptance criteria                                                                                      | Result | Remarks               |
|----------------------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Original Declaration of Conformity)                                                  | Pass   | Available             |
| 2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion.                | Pass   | Found good condition. |
| 3. Check engine oil level (check for proper oil level)                                                   | Pass   | Found good condition. |
| 4. Check for Descending and Leveling output, Rated current(DCA), Rated voltage(DCV), Rated duty cycle(%) | Pass   | Found good condition. |
| 5. Check for Accessorial Receptacle                                                                      | Pass   | Found good condition. |

➤ **Conclusion:**

The **GENERATOR** found in good running condition at the time of Inspection.  
Provide Inspection reports copy for site assessments.

Inspected by:

Checked by:

MOHAMED OMARA  
IVS - Inspector



IVS- Team Leader

Date of issue: 21 JAN 2021

**Inspection centre:** BUREAU VERITAS ALKHOBAR