



INSPECTION REPORT

NO. R109210712.02

BV Job nr: KHO.INI.21.SA.

PROJECT: Third Party Inspection for GENERATOR	Ref: KHO.INI.21.SA.
BV Client: Sudhir Rental	P/o nr: N/A (client to BV)
Manufacturer: PERKINS	P/o nr: N/A (client to Manufacturer)

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No.:	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERATOR	VEPL/2021-20/0006	SG-519-500	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: Yes No

Title	Reference n°	Rev.	Approved by	Date
ORIGINAL DECLARATION OF CONFORMITY	-	-	-	-

INSPECTIONS : Inspection place & Date or Period: Dammam July 12, 2021 Stage of inspection : Before manufacturing During manufacturing Final Packing Type of inspection: Pre-inspection meeting Document and QC record review Visual examination, checks Witnessing tests Manufacturing progress status Vendor assessment Final inspection Packing (for details see continuation sheet) Stamping: No	Results of inspection : Satisfactory Unsatisfactory Non Conformities Reports (NCR): ☐ NCR's issued during reported period : N/A ☐ List of outstanding NCR's : N/A Main Conclusions & Remarks: (for details see continuation sheet) Visual inspection and Function test was done for Generator and found satisfactory at the time of Inspection. Valid Sticker Number : 20-26928 Next visit scheduled: Jan 11 ,2022
--	--



BUREAU
VERITAS

INSPECTION REPORT

NO. R109210712.02

Interim
Final

BV Job nr: KHO.INI.21.SA.

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Rental on the purpose of Third Party Inspection .

2. Scope of Inspection :


a. Visual Inspection & Functional Test of GENERATOR

1- General Data	
Equipment Type	Diesel Generator
Manufacturer	PERKINS
Serial No.	VEPL/2021-20/0006
Owner ID No	SG-519-500
RATING	500 KVA

2- Inspection and Test Results		
Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.	Pass	Found good condition.
3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.

➤ Conclusion:

The GENERATOR found in good condition at the time of Inspection.

Inspected by: Mohamed Omara LIFTING EQUIPMENT INSPECTOR   Issued at Al Khobar office on July 12,, 2021	Checked by: OPERATION TEAM LEADER 
--	--