

## FITNESS CERTIFICATE

### Physical and Visual inspection of Diesel Generator

Certificate No.: AVKSA-C-04-23-0136-003

Date of Inspection: 10/04/2023

|                                                                                                                                     |                                |                                                                  |                                         |
|-------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|------------------------------------------------------------------|-----------------------------------------|
| <b>Name and Address of the Owner:</b><br><br>SUDHIR EQUIPMENT RENTAL CO.<br>P.O. Box 1723, DAMMAM -31441<br>KINGDOM OF SAUDI ARABIA |                                | <b>Place of Inspection:</b><br>NEOM DUBA                         | <b>Sticker No.</b><br>92844             |
|                                                                                                                                     |                                | <b>Maker &amp; Date of Manufacture:</b><br>VARADA ENERGIES -2022 | <b>Ref. Standard:</b><br>NFPA 110       |
| <b>Registration No.:</b><br>N/A                                                                                                     | <b>Owner No.:</b><br>SG-574-60 | <b>Model No.:</b><br>LGDF1072                                    | <b>Serial No.:</b><br>VEPL/2021-22/0076 |
| <b>DETAILS OF THE EQUIPMENTS / DESCRIPTION</b><br>Diesel Engine Generator<br>KVA : 62.5                                             |                                |                                                                  |                                         |

#### SUBJECT: INSPECTION OF GENERATOR

This is to certify that the undersigned, a competent representative did attend to examine this equipment to ascertain the safe working condition of the equipment. At the time of examination indicated, the said equipment has no indigenous injury or sighted deformation. The equipment is safe for its intended use within the limits specified, provided there is a continuous maintenance applied and qualified operators employed.

#### OBSERVATION:


The above equipment and its accessories were visually inspected and found to be Satisfactory for further use. All the safety devices and warning lights were working satisfactory. Inspection carried out and report issued without prejudice to the rights of whomsoever it may concern for and on behalf of Velosi Saudi Arabia Co. Ltd.

#### Recommendations and Overall Condition Assessment

| Date of Last Visual Examination | Next Inspection Due |
|---------------------------------|---------------------|
| 21/03/2023 (UIC)                | 09/04/2024          |


|                           |                              |                      |
|---------------------------|------------------------------|----------------------|
| Date of Issue: 11/04/2023 | JOB NO.: AVKSA-WO-04-23-0136 | Timesheet No.: 17905 |
|---------------------------|------------------------------|----------------------|

Authorized Name: Nafa Alrowaie

Authorized Signature: 



Surveyor's Name: AWAIS KHALID

Surveyor's Signature: 

**THIS IS TO CERTIFY THAT** the above signed competent surveyor thoroughly examined the lifting equipment in the above-mentioned place as per the Technical Regulation and Standard. The liabilities and insurance are as per Velosi Saudi Arabia General Conditions of Services.