

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 14-06-2025		Date of issue : 14-06-2025		Report No. : ESICO-LFT-R25-4307	
Name & Address of employer		Location		Sticker No	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh		5959	SASO ISO EN 280
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name	
SJ12ESL-625 OR B200054865	SCISSOR LIFT MODEL: 3246ES Engine power: 48KW Max. number of occupants: 2 Max.working height: 9.68m Nom,batt,voltage: 24V D.C Max.allowable side force: 400N Max.wind speed: 12.5m/s	317 kg	2019	JLG	
Is this the first examination after installaton or assembly at a new site or location? Yes ☐ - ☐ No ☒		Was the examination carried out within an interval of? - 6 Months			
If the answer to the above question is YES, has the equipment been installed correctly? Yes ☐ - ☐ No ☐		In accordance with an examination scheme? Yes ☒ No ☐			
		After the occurence of exceptional circumstances? Yes ☐ - ☐ No ☒			
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?					N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory					



For confirmation scan QR code
search with report number : **ESICO-LFT-R25-4307**

☒ Safe to operate

Next Inspection : 13-12-2025

Inspected by : Mohamed Askar Ali

