



LIFTING EQUIPMENT INSPECTION REPORT

SNDHIR

JLG

DANNOM

Equipment Name: SJ12ESL-626

3246ES

Nov 08, 2022

▷ MM YARD

320 K 6

MC up

9,000

☒ Pass☐ Fail

B 2000 37672

No. 5274 Issued By

Sticker No. 80-21-6907

MAY 07, 2023

Manufacturer JLG	Model 3246ES	320KG	MCmp	B 2000 51612	ASME and API Standards.
Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's					ASME and API Standards.
Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.					CORRECTIVE ACTION TAKEN

[illegible]

RECEIVER NAME: TASSER

SIGNATURE:..

SIGNATURE:.....
TELEPHONE No.:.....0552228037

INSPECTOR NAME:

... TELEPHONE No.:

BADGE#:

8031

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency