



Previous Sticker
No. 27-9649 Issued By BV

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. 21-1649 Issued By BU
	UQAYER	DEC 03, 2023		15:30	
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHJR	S20AJ-633	SPARCITY		☒ Pass ☐ Fail	BU-23-0040
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	600 AJ	5000 LB	MEWP	0300140135	JUNE 02, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]