



Previous Sticker
No. 217606 Issued By BV

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date SEP 05, 2023		Inspection Time 8:30	Previous Sticker No. 21 + 606 Issued By BV
Department / contractor SUADHIR	Equipment Number S16AG-639	Equipment Location DAMMAM		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-9509
Manufacturer GENIE	Model Z4525RT	Capacity 227KG	Type HCUW	Equipment Serial Number Z4525RT-1875	Sticker Expiration Date MARCH 04, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Periodic inspection and function test for Boom supported elevating work platform AS Per AS STANDARD 617-30, ANSI 92.5 "ROSS" 7	

RECEIVER NAME: ARIF SIGNATURE: [Signature] INSPECTOR NAME: Wienisky
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 191 0000