



**BV No.** 236666

|                                        |                  |                    |        |                                                                        |                         |
|----------------------------------------|------------------|--------------------|--------|------------------------------------------------------------------------|-------------------------|
| LIFTING EQUIPMENT<br>INSPECTION REPORT | Area             | Inspection Date    |        | Inspection Time                                                        | Previous Sticker        |
|                                        | JUBAIL           | AUG 22, 2023       |        | 10:00                                                                  | No. 7387 Issued By BU   |
| Department / contractor                | Equipment Number | Equipment Location |        | Equipment Result                                                       | New Sticker No.         |
| SKDHJR                                 | S26AJ-654        | APOC               |        | <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail | BU-21-8677              |
| Manufacturer                           | Model            | Capacity           | Type   | Equipment Serial Number                                                | Sticker Expiration Date |
| JLG                                    | 600AJ            | 5002BC             | Hybrid | B300017845                                                             | FEB 21, 2024            |

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]