



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY (REVISION 2)

Date of thorough examination : 08-07-2025	Date of issue : 08-07-2025	Report No. : ESICO-LFT-R25-4654
---	----------------------------	---------------------------------

Name & Address of employer		Location	Sticker No	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh	6306	SASO ISO EN 280
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
S18AJ-658 OR B300017875	MAN LIFT TYPE: ARTICULATED MODEL: S20AJ Max. allowable side force: 400N Max. wind speed: 12.5m/s Max. platform height: 16 m Max. working height: 18m Max. occupation person: 2	RATED LOAD : 250 KG	2022	JLG

Is this the first examination after installaton or assembly at a new site or location?	Yes - No ☒	Was the examination carried out within an interval of? - 6 Months	Yes ☒ No -
If the answer to the above question is YES, has the equipment been installed correctly?	Yes - No -	In accordance with an examination scheme?	Yes ☒ No -
		After the occurrence of exceptional circumstances?	Yes - No ☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory	



For confirmation scan QR code
search with report number : ESICO-LFT-R25-4654

☒ Safe to operate

Next Inspection : 07-01-2026

Inspected by : Mohamed Askar Ali

