



Previous Sticker
No. 21-9331 Issued By BU

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	TAMAJIB	JAN 18. 2024		10:30	No. 21-9331 Issued By BU
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDAJE	5285J-689	MARJAN		☒ Pass ☐ Fail	BU-23-0846
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	860SJ	5000LBS	MEWP	B300014215	JULY 17. 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for Beam supported elevators work part form. AS per as SORANG GT 7030, AMS 92.5	
	Pass	

RECEIVER NAME: DRH SIGNATURE: [Signature] INSPECTOR NAME: M. [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 100