



Previous Sticker
No. 21-6620 Issued By Bu

LIFTING EQUIPMENT INSPECTION REPORT	Area DORM M	Inspection Date AUG 16, 2023		Inspection Time 17:00	Previous Sticker No. 21-6620 Issued By BU
Department / contractor SUDAIR	Equipment Number S285J-698	Equipment Location DMY WPD		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-21-8659
Manufacturer JLG	Model 860SJ	Capacity 500 LBS	Type MEWP	Equipment Serial Number B3000 13861	Sticker Expiration Date FEB 15, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Periodic inspection and function test for Beam supported elevating work platform AS Per AS 5081:2006 6.7.3.2.5 Pass	

RECEIVER NAME: THAS SGER SIGNATURE: [Signature] INSPECTOR NAME: Michael
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 18-c-009