



Previous Sticker
No. 21-7726 Issued By [Signature]

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date Aug 30, 2023		Inspection Time 9:00	Previous Sticker No. 21-7726 Issued By [Signature]
Department / contractor Sudhir	Equipment Number S18AT-718	Equipment Location DMMYWRN		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-21-8693
Manufacturer JLG	Model S20 AT	Capacity 500 LBS	Type MEWP	Equipment Serial Number B300017684	Sticker Expiration Date FEB 28, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection and function test for BOOM Supported elevating work platform. AS Per AS S.AROMCO G17.030, ANSI 92.5 "PASS"	

RECEIVER NAME: APR SIGNATURE: [Signature] INSPECTOR NAME: M. M. M.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019106