



LIFTING EQUIPMENT INSPECTION REPORT		Area	Inspection Date	Inspection Time	Previous Sticker No.	Issued By
Department / Contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.	
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date	

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
4	Initial Inspection and function test for Beam Support (cladding) were not done. As per AS S-000000 657-034 was 8592.5 PASS	

RECEIVER NAME: <u>TANJEE</u>	SIGNATURE: <u>[Signature]</u>	INSPECTOR NAME: <u>M. [Signature]</u>
BADGE#: _____	TELEPHONE No.: _____	TELEPHONE No.: <u>18009</u>