

NATIONAL INSPECTION AND TECHNICAL TESTING COMPANY

CERTIFICATE OF TEST & EXAMINATION OF MOBILE ELEVATING WORK PLATFORM

CERTIFICATE NO. : LIC-2026-6124

STICKER NO.: F-WR-002144

DATE OF ISSUE: 28-02-2026

Name and Address of the Client	:	SUDHIR COMPANY FOR EQUIPMENTS RENTAL / 32221 Dammam - Additional # 9062
Work Order No.	:	FAHSS-26-2602
Type of Inspection	:	Periodic
Location of Inspection	:	USFAN - SUDHIR YARD
Type of Equipment	:	BOOM SUPPORTED ELEVATING WORK PLATFORM
Capacity	:	230KG
Name of Manufacturer / Model Number	:	JLG 1350SJP
Year of Build	:	2017
Serial Number	:	0300230767
Owner ID No	:	S43SJP-733
Motive Power	:	DIESEL/HYDRAULIC
Reference Standard	:	ANSI/SAIA A92.5 , SASO GSO EN280
Measuring Equipment ID	:	MEASURING TAPE ID# IIS-00016, REPORT#14082 ,VERNIER CALIPER ID# IIS-00007, CERT.24-73050

DESCRIPTION	Maximum Working Height (m)	Maximum Horizontal Reach (m)	TEST LOAD (kg)	SWL (kg)
Aerial Work Platform type: Boom Supported, Telescopic boom manlift on tires, Max.No. of person: 02, Basket/platform rotation: 180°, Platform size (Inner): 2.44m(L) X 0.91m(W), Machine weight: 20080kg.	43.3	24.38	Nil	230

Inspection Date	Next inspection Date	Ref. and Date of Last Thorough Examination	Ref. and Date of Last Proof Load Test	Next Proof Load Test Date
26-Feb-2026	25-Aug-2026	10-Aug-2025	21-Jan-2024	AFTER MAJOR REPAIR

This is to certify that the above **BOOM SUPPORTED ELEVATING WORK PLATFORM** was tested and thoroughly examined and no defect affecting its safe use was found at the time of inspection. The equipment is **safe to operate** up to its SWL and for its intended use within the design limits specified, provided there is continuous maintenance applied and a qualified operator is employed. This document is valid until the date of next inspection or the date of expiry of thorough examination or the date from which any major repair / alteration is done to the equipment; whichever occurs earlier.

Inspected by: Waseem N. Rakhang




Reviewed by: Yaser Kahfazan



On Behalf of FAHSS

"This document is issued subject to the condition that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, repairer or operator of any warranty, express or implied and National Inspection and Technical Testing Company. (FAHSS) liability shall be limited to the acts or omissions of its employees, agents and sub contractors. FAHSS shall in no event be liable for any injury or damage to any person or property occurring by reason of negligent operation or lack of proper maintenance or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted testing standards and only upon those items actually inspected by FAHSS and which are covered under this document."

ELEVATING WORK PLATFORM INSPECTION CHECKLIST

Owner ID No. / Plate No.	S43SJP-733 / N/A	Date	26-Feb-2026
Maker Ser. No.	0300230767	Report No.	LIC-2026-6124

No	Examination Items	S	NS	N/A	Defects Found / Comment
Risk Assessment					
1	Work permit	☒	☐	☐	
2	Inspection area is isolated and safe for inspection and testing	☒	☐	☐	
3	Operator is certified to operate the inspected equipment	☒	☐	☐	
4	Operator informed not to move any part of the equipment unless informed by the inspector for safe operation	☒	☐	☐	
5	Dropped Objects, Overhead Powerlines	☒	☐	☐	
6	Beware of Slips and trips, Rotating machineries	☒	☐	☐	
7	Observe High wind status	☒	☐	☐	
Inspection Checklist					
8	General Condition	☒	☐	☐	
9	Documentations and Operation Manual	☒	☐	☐	
10	Identification Labels on Controls	☒	☐	☐	
11	Ground Control Console	☒	☐	☐	
12	Platform Control Console	☒	☐	☐	
13	Motion Warning / Reverse Alarm / Horn	☒	☐	☐	
14	Emergency Descending System	☒	☐	☐	
15	Level Indicator	☒	☐	☐	
16	Boom/Jib/ Scissor Structure	☒	☐	☐	
17	Tilting Sensor	☒	☐	☐	
18	Personnel Cage Platform & Anchoring Point	☒	☐	☐	
19	Articulated Jib	☐	☐	☒	
20	Swing Machinery	☒	☐	☐	
21	Turntable Bearing	☒	☐	☐	
22	Overload Limit / Anti Entrapment Device / Safety Devices	☒	☐	☐	
23	Outriggers / Stabilizer	☐	☐	☒	
24	Tires	☒	☐	☐	
25	Brakes	☒	☐	☐	
26	Hydraulic System Hoses	☒	☐	☐	
27	Electrical Integrity	☒	☐	☐	
28	Structural Integrity / Corrosion / Paint work	☒	☐	☐	
29	Maintenance Log	☒	☐	☐	

Note: S= Satisfactory / Accepted | N.S. =Not Satisfactory | N/A = Not Applicable

Inspected by: Waseem N.
Rakhange




Reviewed by: Yaser Kahfazan



On Behalf of FAHSS

Reference Standard : ANSI/SAIA A92.5 , SASO GSO EN280

NATIONAL INSPECTION AND TESTING COMPANY (FAHSS), P.O. Box 3998, DAMMAM 32252, Kingdom of Saudi Arabia

Contacts: +966 (13) 340 7607 | +966 (12) 6109014 | +966 (14) 325 1475 | +966 538400764

EMAIL: info@fahss.com

FAHSS-IIS-LIC-FRM-049 Rev 3 20/05/2025



NO.: F-WR-002144

EQUIP.NO.: S43SJP-733

EQUIP. S.N.: 0300230767

DATE INSPECTED: 26-Feb-2026

NEXT INSPECTION DATE: 25-Aug-2026

INSPECTED BY: Waseem N. Rakhange