



BUREAU
VERITAS

BV No. 236944

LIFTING EQUIPMENT INSPECTION REPORT	Area JAFUR	Inspection Date DEC 07, 2023		Inspection Time 15:00		Previous Sticker No. 21-8745 Issued By BV
	Department / contractor SINAR	Equipment Number S40SG-748	Equipment Location JCB-5		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0054
Manufacturer GENIE	Model SX-125 Xc	Capacity 227KG	Type MEWP	Equipment Serial Number SX125D-1259		Sticker Expiration Date JUNE 06, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards.
Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and function test for	
	Beam SUPPORTED (leveling) were not found	
	AS PERAS S. ORANGE G770 3.1.10.192.5	
	"Pass"	

RECEIVER NAME: ARIF SIGNATURE: [Signature] INSPECTOR NAME: M. [Signature]
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 86019166