



BV No. 236211

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	Dammam	JUN 23, 2023		01:00	No. Initial Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHIR	S405G-749	SUDHIR yard		☒ Pass ☐ Fail	BV-21-8746
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GENIE	SX-125 XC	300 KG	manlift	SX125D-1036	DGC 22, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

[illegible]