

Certificate of Visual Examination

Client Name :		
Branch of Sudhir Rental		
Work/ Rig Location:	Certificate Number:	Issued Sticker No.(if Applicable)
DMM SUDHIR YARD	ZM-20-Z085 414	W.9345
Date of Last Inspection	Date of Inspection:	Date of Next Inspection:
INITIAL	4-Jul-2023	3-Jan-2024
Relevant Standards:	O.E.M / C.O.C / Reverse Engineering Cert. No.	Color Code (If Applicable for the item) (Current applicable Color at the Time of Inspection)
ANSI A92.5	MANUFACTURER MANUAL	
Zamil Ref No.	Customer Requisition No.	N/A
ZAM-2812-07-23	N/A	

I.D. NUMBER	QTY	DESCRIPTION	SWL / CAPACITY
S40SG-752	1	MANLIFT DIESEL POWERED HYDRAULIC,TELESCOPIC BOOM WORK PLATFORM (ELEVATING WORK PLATFORM) MAKE: GENIE MODEL: SX125XC S/N: SX125D-897	300 Kg
NOTE : Visual Inspection & Functional Test Were Carried Out as per client request On The Above Mentioned Equipment , At The Time Of Inspection No Any Abnormality Found.			

Result: During the Time of Visual Inspection, Result found Satisfactory.

This Certificate by Company Under Its General Conditions of Services. This Issuance of This Certificate Does Not Exonerate the Buyers or Sellers from Exercising All Their Rights Discharging All Their Liabilities Under the Contacts of Sale. Stipulations to Contrary Are Not Binding on The Companies Responsibility Under This Certificate. It is Limited to Proven Negligence and Will in No Case Be More Than Ten Times the Amount of The Free or Commission. The Above Findings Are Limited to Date Place of Intervention Only. The Company Is Neither an Insurer Not a Guarantor Disclaims All Liabilities in Such Capabilities.

Inspected By:
Name : Hassan Al Gudaihi
Qualifications : LEEA & ASNT NDT Level II Certified

Signature & Stamp:





طريق الملك فهد - حي الضباب - الدمام - س.ت: 2050069798 - ص.ب 419 - الدمام 31411

King Fahad Road - Al-Dhabab Avenue - Dammam - C.R.: 2050069798 - P.O. Box 419 - Dammam 31411 Email: info@zamil.sa