



LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date Oct 26, 2023		Inspection Time 10:00	Previous Sticker No. 21-9302 Issued By B
Department / contractor SUDAIR	Equipment Number S40SG-757	Equipment Location DMM YARD		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-21-974
Manufacturer GENIE	Model SX125-Xc	Capacity 227kg	Type MEWP	Equipment Serial Number SX125D-1097	Sticker Expiration Date APR 25, 2024

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic Inspection and Function Test for Beam Supporter Clevis Work Part Done As per S.C. Range Cat 7.030, ANSI 92.5 PASS	

RECEIVER NAME: ARH SIGNATURE: Am INSPECTOR NAME: M. B. B. B. B.
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 19106