



Client Name & Address:	SUDHIR EQUIPMENT RENTAL COMPANY -RAS ALKHAIR		
Work Order No.	ZAM-3387-09-23	Report No.	ZAMIL-R03907 / VIS
Place Of Inspection	RAS ALKHAIR SUDHIR	Report Date	19/09/2023
Date of Last Inspection	25-07-2023	Date of Inspection	18/09/2023
Customer Requisition No.	N/A	Date of Next Inspection	17/03/2024
Applicable Standards	ANSI A92-5	Issued Sticker No.	N/A
O.E.M / C.O.C No. / Drawings	Available	Color Code (If Applicable)	NA
Equipment Used	Vernier Caliper	Model No.	SX-125XC

Equipment Serial No.	Equipment I.D	QTY	Description	Capacity/SWL (Ton)
SX1250-1097	S40SG-757	01	Man Lift	1000 LBS
			Diesel Powered Articulated Boom Supported Personnel Elevating Work Platform Max Capacity : 1000 LBS Max Platform Height : 125 FT Max Horizontal Reach : 80 FT Manufacturer : TEREX MACHINERY CO Machine Weight : 45490.52 LBS Year Of Manufacturer : 2019 Note : Visual inspection and functional test has been performed on the above mentioned equipment, during the time of inspection no any abnormality found.	

Is this the first examination after installation or assembly at a new site or location:	☐ YES ☒ NO
If the answer to the above question is YES. Has the equipment been installed correctly?	☐ YES ☐ NO ☒ NA
Was the thorough examination carried out Within an interval of 3 months?	☐ YES ☒ NO
Was the thorough examination carried out Within an interval of 6 months?	☒ YES ☐ NO
Was the thorough examination carried out Within an interval of 12 months?	☐ YES ☒ NO
In accordance with an examination scheme?	☒ YES ☐ NO
After the occurrence of exceptional circumstances?	☐ Yes ☒ No
Identification of any part found to have a defect which is or could become a danger to person and a description of the defect (if none state none): NONE	
Is the above a defect which is of immediate danger to persons	☐ YES ☒ NO
Is the above a defect which is not yet but could become a danger to persons? (If yes state the day by when)	☐ YES ☒ NO Date: N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE): NONE	
Inspection Result:	During the time of Inspection Result found satisfactory - Is this Equipment Safe to Operate? ☒ YES ☐ NO
This certificate by company under its general conditions of services. This issuance of this certificate does not exonerate the buyers or sellers from exercising all their rights discharging all their liabilities under the contacts of sale. Stipulations to contrary are not binding on the company's responsibility under this certificate is limited to proven negligence and will in no case be more than ten times the amount of the free or commission. The above findings are limited to date place of intervention only. The company is neither an insurer not a guarantor disclaims all liabilities in such capabilities.	

Inspected By Qualified: LEEA & ASNT NDT Level II		Reviewed By		Stamp
Name:	Ahmed Rashad	Name:	Mohamed Atwa	
Position:	Inspector	Position:	Technical supervisor	
Signature:		Signature:		



Name and address of employer of persons making and authenticating this report: Zamil Inspection & Contracting Co, King Fahad Road-Al-Dhabab Avenue-Dammam 32261
C.R.: 2050069798-Email: operations@zamil.sa



Zamil Inspection & Contracting Co.



+966555052687



info@zamil.sa



NO. ZAM-W-14981

Equipment Type : Man Lift
capacity/SWL : 1000 LBS
Equipment ID : S40SG-757
Equipment S.N. : SX1250-1097
Inspection Date : 18/09/2023
Next Insp Date : 17/03/2024
Inspected By : Ahmed Rashad



Corporate Partner