



BUREAU
VERITAS

BV No. 236219

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAN	Inspection Date JUN 26, 2023		Inspection Time 08:00	Previous Sticker No. Initial Issued By
	Department / contractor Subhir	Equipment Number 540SG-758	Equipment Location Subhir yard	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-8754
Manufacturer GENIE	Model SX-125XC	Capacity 300 KG	Type MAN LIFT	Equipment Serial Number SX125D-1263	Sticker Expiration Date DGC 25, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
#	Initial Inspection & Functional tests were carried out on Boom	
	supported elevating work platform As per ASME A92.5 &	
	Aramco GI 7.530 and the equipment was found satisfactory	
	at the time of inspection.	
	Manufacturer documents and Load test certificate were verified onsite.	
	Follow proper PM procedure regularly & maintain good house keeping	

RECEIVER NAME: CHAISER SIGNATURE: [Signature] INSPECTOR NAME: [Signature] 8009129

BADGE#: 8031 TELEPHONE NO.: 055 2228031 TELEPHONE NO.: 0550183638

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency