



BUREAU
VERITAS

BV No. 236220

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAN	Inspection Date JUN 26, 2023	Inspection Time 10:00	Previous Sticker No. Initial Issued By
Department / contractor SudWR	Equipment Number 54056-759	Equipment Location SudWR yard	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-8755
Manufacturer GENIE	Model SX-125 XC	Capacity 300 KG	Type manlift	Equipment Serial Number SX125D-1104
				Sticker Expiration Date DGC 25, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
#	Initial inspection & functional tests were carried out on	
	Boom supported elevating work platform as per ANSI A92.5	
	and Aramco GI 7-530 and the GWP met was found	
	"satisfactory" at the time of inspection	
	Manufacturer documents and Load test certificate were verified on site	
#	Follow proper PM procedure regularly & maintain good house keeping	

RECEIVER NAME: **CHAISSER** SIGNATURE: **[Signature]** INSPECTOR NAME: **Ahmed Zarebun**
 BADGE#: **8031** TELEPHONE NO.: **555 222 8031** TELEPHONE NO.: **555 0183638**

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency