



BUREAU
VERITAS

BV No. 239211

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date JAN 29, 2024		Inspection Time 14:30	Previous Sticker No. 32112 Issued By
Department / contractor SUDHAR	Equipment Number S40SG-759	Equipment Location DMMHAR		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0870
Manufacturer GENIE	Model SX-125XC	Capacity 300KG	Type MEWP	Equipment Serial Number SX125D-1104	Sticker Expiration Date JULY 28, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Initial Inspection and function test for	
	Boom supported elevating work platform	
	AS Per ASME B30.30, 10.5.1.5	
	' Pass'	

RECEIVER NAME: ARTF	SIGNATURE:	INSPECTOR NAME: M. Alharbi
BADGE#:	TELEPHONE NO.:	TELEPHONE NO.: 800191006