



BUREAU
VERITAS

BV No. 236221

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date JUN 26, 2023	Inspection Time 12:00	Previous Sticker No. Initial Issued By
Department / contractor Sudhir	Equipment Number S40SG-760	Equipment Location Sudhir yard	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-8756
Manufacturer GENIE	Model SX-125XC	Capacity 300 KG	Type MAN LIFT	Equipment Serial Number SX125D-1090
				Sticker Expiration Date DEC 25, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
#	Initial Inspection & Functional tests were carried out on Boom	
	supported elevating work platform as per ANSI A92.5 &	
	Aramco GI 7.53 and the equipments were found "satisfactory"	
	at the time of inspection	
	Manufacturer documents & Load test certificate were verified on site	
#	Conduct proper PM procedure regularly & maintain good house keeping	

RECEIVER NAME: **CHAISEER** SIGNATURE: **[Signature]** INSPECTOR NAME: **20019129 Ahmed Zoubeir**
 BADGE#: **8031** TELEPHONE NO.: **0552228031** TELEPHONE NO.: **0550183638**

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agency