



Previous Sticker
No. 2017a Issued By

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. <u>SW174</u> Issued By
	<u>DAMPYON</u>	<u>AUG 30, 2023</u>		<u>10:30</u>	
Department / contractor <u>SUDHJR</u>	Equipment Number <u>S16AG-762</u>	Equipment Location <u>DMN YARD</u>		Equipment Result ☒ Pass ☐ Fail	New Sticker No. <u>BV-21-8694</u>
Manufacturer <u>GENIE</u>	Model <u>Z4525RT</u>	Capacity <u>227KG</u>	Type <u>MEWP</u>	Equipment Serial Number <u>Z4525D-2508</u>	Sticker Expiration Date <u>FEB 28, 2024</u>

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Initial inspection and function test for Boom Support and Clevises were performed. AS per AS S. ARM Co G17.0 301 was 92.5 Pass	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: M. Otrons

BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800-19106