



Previous Sticker
No. 19772 Issued By Zamb

LIFTING EQUIPMENT INSPECTION REPORT	Area DMM	Inspection Date JAN 06, 2024		Inspection Time 9:00	Previous Sticker No. 19772 Issued By Zant
	Department / contractor SVO HJR	Equipment Number S22SG-767	Equipment Location DMM YARD	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-23-0813
Manufacturer GENIE	Model S65	Capacity 227K	Type MEWP	Equipment Serial Number S60D-879	Sticker Expiration Date JULY 03, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Periodic inspection and function test Per Beam supported Elevation work per form AS per AS S.D.RANGE GJ7.030 AMST 92.5 <u>Pass</u>	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: [Signature]
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 466 6666