



BUREAU
VERITAS

BV No. 239242

LIFTING EQUIPMENT INSPECTION REPORT	Area Dammam	Inspection Date FEB 12, 2024		Inspection Time 12:00	Previous Sticker No. 21-8637 Issued By BV
Department / contractor SUDAIR	Equipment Number 543 AG-780	Equipment Location Dammam		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0897
Manufacturer GENIE	Model Z-135	Capacity 272KL	Type MEWP	Equipment Serial Number Z13512-1645	Sticker Expiration Date AUG 11, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic inspection was function test for	
	Boom supported & clearly work at 1st boom	
	As per as sample (077-20005925	
	'Rods'	
	→	

RECEIVER NAME: M. ALI SIGNATURE: A INSPECTOR NAME: M. ALI
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 80019106