



LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DAMMAN	AUG 17, 2023		17:00	No. 321212 Issued By
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDAIR	S43AG-801	DMMYARD		☒ Pass ☐ Fail	BV-21-8663
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GENIE	Z-135	227KG	MEWP	Z13512-1681	FEB 16, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
#	Initial inspection and function test for Beam supported elevating work platform from VSP Per AS S.A.R.M.C. G17.030, AWS 92.5 PASS	

RECEIVER NAME: T/HAJSEER SIGNATURE: [Signature] INSPECTOR NAME: M. M. M. M.
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 180009