



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

Date of thorough examination : 12-07-2025	Date of issue : 12-07-2025	Report No. : ESICO-LFT-R25-4920
---	----------------------------	---------------------------------

Name & Address of employer		Location	Sticker No	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh	6572	BS EN 60034- 22: 2009
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
STL-420 OR VEPL/2023-24/281	TOWER LIGHT ATTACHED WITH GENERATOR MODEL:SGL-7.5 TOWER HEIGHT: 8.5MTR VOLTS: 230,1PHASE MASS: 2800KG	N/A	2023	VARADA ENERGIES

Is this the first examination after installaton or assembly at a new site or location?	Yes - No ☒	Was the examination carried out within an interval of? - 6 Months	Yes ☒ No -
If the answer to the above question is YES, has the equipment been installed correctly?	Yes - No -	In accordance with an examination scheme?	Yes ☒ No -
		After the occurence of exceptional circumstances?	Yes - No ☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : At the time of inspection tower light was found to be of good condition and reliable for safe operation	



For confirmation scan QR code
search with report number : ESICO-LFT-R25-4920



☒ Safe to operate

Next Inspection : 11-01-2026

Inspected by : Mohamed Askar Ali

