



CERTIFICATE OF THOROUGH EXAMINATION

TOWER LIGHT

CERTIFICATE / REPORT NO : CRT-105473

STICKER NO : 87868

JOB NO : WO-28836

EQUIPMENT OWNER : 24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE SUDHIR RENTALS -24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE		TYPE OF INSPECTION : PERIODIC VISUAL AND FUNCTIONAL INSPECTION	
LOCATION: DAMMAM YARD	DATE OF INSPECTION : 25-Nov-2023	Frequency 6 month	Next Inspection Due 24-May-2024
EQUIPMENT DESCRIPTION : 1 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE DIESEL ENGINE POWERED TOWER LIGHT OF WATTAGE CAPACITY 4 X 400 W.			
MANUFACTURER : VARADA ENERGIES PVT LTD	MODEL/TYPE : SGL-7.5	MANUFACTURED YEAR : 2023	
SERIAL NO : VEPL/2023-24/311	OWNER ID : STL-463	WORK PROCEDURE NO : SA-WP-06	
REFERENCE STANDARDS : ISO 8528-13:2016	DATE OF PREVIOUS INSPECTION :	PREVIOUS INSPECTION DETAILS: NEW	

WATTAGE: 4 X 400 W	FUEL TYPE: DIESEL
LIGHTING TOWER HEIGHT - 8.5 METERS	MASS - 2800 KG
RESULT : SATISFACTORY-PASS	CHECKLIST NO : 44530
REMARKS/RECOMMENDATION : PRE-OPERATIONAL CHECK FOR GENERAL CONDITION AND WORKING OF THE EQUIPMENT IS RECOMMENDED BEFORE EACH USE.	

Reviewed By : MOHAMED ANWAR DEEN

Authorised Inspector : LIJO MATHAI CHERIAN



SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE
SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE
SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE
SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE
SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SERIAL NO: VEPL/2023-24/311 VALID TILL : 24-May-2024 Report No: CRT-105473 SE

THIS CERTIFICATE BECOMES INVALID, IF ANY ALTERATION/REPAIR OR MODIFICATION IS MADE TO THE EQUIPMENT

THE CONCERNED INSPECTOR OR REPRESENTATIVE HAS THOROUGHLY EXAMINED THE EQUIPMENT IN ACCORDANCE TO THE RELEVANT STANDARDS. EXAMINATION INDICATES THAT THE SAID EQUIPMENT HAS NO APPARENT DEFECTS OR DEFORMATION WHICH MAY PROVE DANGEROUS DURING NORMAL OPERATION. THE SAID EQUIPMENT IS FOUND TO BE SATISFACTORY FOR FURTHER USE, PROVIDED THERE IS REGULAR MAINTENANCE AND OPERATED BY A CERTIFIED OPERATOR. THIS CERTIFICATE IS GRANTED SUBJECT TO THE CONDITION THAT IS AGREED & UNDERSTOOD THAT STANDARD ARABIA INSPECTION CO. LTD.'S LIABILITY SHALL BE LIMITED TO THE ACTS OF ITS EMPLOYEES ON PREMISES OF SUBCONTRACTORS. UNDER NO CIRCUMSTANCES WHATSOEVER SHALL STANDARD ARABIA INSPECTION CO. LTD. BE LIABLE FOR ANY INJURY OR DAMAGE TO ANY PERSON OR OCCURRING AS A RESULT OF NEGLIGENCE OPERATION OR ANY DEFECT IN MATERIALS, MACHINERY, EQUIPMENT OR SYSTEMS OTHER THAN DEFECTS ASCERTAINABLE DURING ROUTINE INSPECTION. WE HEREBY REPORT THAT THE ALL PARTICULARS IN THIS REPORT ARE CORRECT AT THE TIME OF TEST / INSPECTION & OPERATIONAL MAINTENANCE IS THE SOLE RESPONSIBILITY OF THE EQUIPMENT OWNER.

THIS CERTIFICATE IS GENERATED AND AUTHORIZED ELECTRONICALLY AND CAN BE CONSIDERED AS ORIGINAL. TO VERIFY THE AUTHENTICITY OF THIS CERTIFICATE, PLEASE SCAN THE QR CODE.

